M-1978-079

Permit sign replaced by Operator as requested by the Division during 8/27/2015 inspection (Received: 9/29/2015).

