



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources

1313 Sherman Street, Room 215
Denver, CO 80203

December 7, 2015

Jason Burkey
United Companies of Mesa County
2273 River Road
Grand Junction, CO 81502

RE: Latham-Burkett Pit; DRMS File No. M-1983-013; Receipt of Corrective Action
Documentation

Dear Mr. Burkey,

The Division received your above referenced response in regard to the Compliance Problem cited in the report of the inspection conducted on December 1, 2015. The status of the corrective actions regarding these problems are as follows:

Compliance Problem 1: The mine identification sign was not posted at the entrance of the mine site.

This problem is considered abated as a result of the Operator's submittal of a photo that a proper mine identification sign has been posted by the corrective action date.

If you have any questions, please contact me at (970)252-5025

Sincerely,

Stephanie Mitchell
Environmental Protection Specialist

