July 18, 2016

Wayne Brantley Pioneer Sand Company PO Box 7650 Colorado Springs, CO 80933



1313 Sherman Street, Room 215 Denver, CO 80203

RE: Fedinec Pit, Permit No. M-1977-057, Inspection Problem Abated

Dear Mr. Brantley:

On May 10, 2016 the Division of Reclamation, Mining and Safety (Division) conducted an inspection of the above referenced site. Signs and Markers was cited as a problem in the inspection report for the absence of a mine sign. Corrective actions required that the operator post a sign at the mine entrance that meets Rule 3.1.12(1). The operator shall supply photo documentation that a sign was posted by the corrective action date.

On July 15, 2016 the Division received photo documentation via email that a new sign had been posted at the site. This satisfies the corrective action and it is considered abated.

If you require additional information, or have questions or concerns, please feel free to contact me. Amy Yeldell, at the Division of Reclamation, Mining and Safety, 1313 Sherman St., Room 215, Denver, CO 80203. Direct contact can be made by phone at 970-254-8511 or via email at amy.yeldell@ state.co.us

Sincerely,

Amv Yeldell

Environmental Protection Specialist Department of Natural Resources Division of Reclamation, Mining and Safety

Phone: (970) 254-8511 Fax: (970) 241-1516

Ec: Russ Means, Senior EPS, Grand Junction DRMS

