



STATE OF  
COLORADO

Musick - DNR, Jason <jason.musick@state.co.us>

---

## Terror Creek Loadout, C-1983-059, 3Q 2016 Pond Inspection Report Review Letter

1 message

---

**Musick - DNR, Jason** <jason.musick@state.co.us>

Thu, Oct 20, 2016 at 7:57 AM

To: Doug Smith <Doug.Smith@oxbow.com>

Good morning Doug,

Attached is the Division's review of the above referenced report associated with the Terror Creek Loadout.

Please let me know if you have any questions or comments.

Thanks,  
Jason

Jason Musick  
Environmental Protection Specialist III  
Coal Regulatory Program



P 303.866.3567 x 8134 | F 303.832.8106  
1313 Sherman Street, Room 215, Denver, CO 80203  
[jason.musick@state.co.us](mailto:jason.musick@state.co.us) | <http://mining.state.co.us>



**3Q2016\_Pond.pdf**

125K



## COLORADO

Division of Reclamation,  
Mining and Safety

Department of Natural Resources

1313 Sherman Street, Room 215  
Denver, CO 80203

October 20, 2016

Doug Smith  
Oxbow Mining, LLC.  
P.O. Box 535  
Somerset, CO 81434

RE: **Oxbow Mining, LLC, Terror Creek Loadout, Permit C-1983-059**  
**Third Quarter 2016 Pond Inspection Report Review**

Dear Mr. Smith:

The Colorado Division of Reclamation, Mining, and Safety (CDRMS) has reviewed and found the above referenced report to be in compliance with the following CDRMS regulation:

4.05.9(17) - Examined at least quarterly by a qualified person designated by the operator, for appearance of structural weakness and other hazardous conditions.

4.05.9(17) - A copy of the report shall be submitted to the Division on a quarterly basis.

The third quarter sediment pond inspection reports were received by the Division on 12 October 2016. Sediment pond inspections were conducted by Oxbow Mining, LLC. on 30 September 2016.

It is noted that no issues were noted and the pond inspections reflect observations noted by the Division.

If you have any questions feel free to contact me. (303) 866-3567 ext 8134

Sincerely,

Jason Musick  
Environmental Protection Specialist

