



STATE OF
COLORADO

Musick - DNR, Jason <jason.musick@state.co.us>

Hayden Gulch Loadout, C-1992-081, 4Q 2016 DMR Review Letter

1 message

Musick - DNR, Jason <jason.musick@state.co.us>
To: Brian Watterson <BWatterson@peabodyenergy.com>

Wed, Feb 8, 2017 at 8:04 AM

Good morning Brian,

Attached is the Division's review of the 4th Quarter 20116 DMR associated with COG-85008 at the Hayden Gulch Mine.

Please let me know if you have any questions or comments.

Thanks,
Jason

--
Jason Musick
Environmental Protection Specialist III
Coal Regulatory Program



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P 303.866.3567 x 8134 | F 303.832.8106
1313 Sherman Street, Room 215, Denver, CO 80203
jason.musick@state.co.us | <http://mining.state.co.us>



4Q16_DMR.pdf
123K



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources

1313 Sherman Street, Room 215
Denver, CO 80203

February 8, 2017

Brian A. Watterson
Peabody Energy, LLC
29515 Routt County Road #27
Oak Creek, CO 84607

RE: **Hayden Gulch Terminal, LLC, Hayden Gulch Loadout, Permit C-1992-081
Fourth Quarter 2016 Discharge Monitoring Report (COG- 850008)**

Dear Mr. Watterson:

The Colorado Division of Reclamation, Mining, and Safety (CDRMS) has reviewed and found the above referenced report to be in compliance with Rule 4.05.13(2). The Fourth Quarter 2016 Discharge Monitoring Report for the above referenced CDRMS Permit was received by the Division on 25 January 2017 via email; the reports cover the time period from 01 October 2016 through 31 December 2016.

During the fourth quarter of 2016 no outfalls discharged.

If you have any questions feel free to contact me. (303) 866-3567 ext 8134

Sincerely,

Jason Musick
Environmental Protection Specialist
Jason.musick@state.co.us

