



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources
1313 Sherman Street, Room 215
Denver, Colorado 80203

April 5, 2017

Jack Henris
Cripple Creek & Victor Gold Mining Company
100 North Third Street
Victor, CO 80860

Re: Receipt of Corrective Action Documentation; Cresson Project; Permit No. M-1980-244

Dear Mr. Henris,

The Division received your response in regards to the Compliance Problem #1 identified in the October 27, 2016, inspection report of the Cresson Project. The status of the corrective action is listed below.

PROBLEM 1: Drain Cover Fill (DCF) has eroded on a northwest portion of the Arequa Gulch Valley Leach Facility and the liner is exposed. The DCF was transported into the trough between the perimeter berm and the toe of the pad, reducing the capacity of this area.

On April 4, 2017, the Operator's submitted a report and photographic documentation showing the erosion feature had been backfilled and the trough appropriately re-established; **this problem has been resolved.**

If you need additional information or have any questions, please contact me at Division of Reclamation, Mining and Safety, 1313 Sherman Street, Room 215, Denver, CO 80203, by telephone at **303-866-3567 x8132**, or by email at elliott.russell@state.co.us.

Sincerely,

Elliott R. Russell
Environmental Protection Specialist

Cc: Cheyne Mann; CC&V
Tim Cazier, DRMS

