



STATE OF  
COLORADO

Musick - DNR, Jason <jason.musick@state.co.us>

---

## Hayden Gulch Loadout, C-1992-081, First Quarter 2017 DMR and Pond Inspection Report Review Letters

1 message

---

**Musick - DNR, Jason** <jason.musick@state.co.us>  
To: Brian Watterson <BWatterson@peabodyenergy.com>

Thu, May 4, 2017 at 8:57 AM

Good morning Brian,

Attached are the Division's reviews of the 1st quarter 2017 DMR and pond inspection report associated with the Hayden Gulch Loadout.

Please let me know if you have any questions or comments.

Thanks,  
Jason

--

Jason Musick  
Environmental Protection Specialist III  
Coal Regulatory Program



**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural Resources

P 303.866.3567 x 8134 | F 303.832.8106  
1313 Sherman Street, Room 215, Denver, CO 80203  
[jason.musick@state.co.us](mailto:jason.musick@state.co.us) | <http://mining.state.co.us>

---

### 2 attachments



**1Q17\_DMR.pdf**  
124K



**1Q17\_Pond.pdf**  
125K



## COLORADO

Division of Reclamation,  
Mining and Safety

Department of Natural Resources

1313 Sherman Street, Room 215  
Denver, CO 80203

May 4, 2017

Brian A. Watterson  
Peabody Energy, LLC  
29515 Routt County Road #27  
Oak Creek, CO 84607

RE: **Hayden Gulch Terminal, LLC, Hayden Gulch Loadout, Permit C-1992-081  
First Quarter 2017 Discharge Monitoring Report (COG- 850008)**

Dear Mr. Watterson:

The Colorado Division of Reclamation, Mining, and Safety (CDRMS) has reviewed and found the above referenced report to be in compliance with Rule 4.05.13(2). The First Quarter 2017 Discharge Monitoring Report for the above referenced CDPS Permit was received by the Division on 27 April 2017 via email; the reports cover the time period from 01 January 2017 through 31 March 2017.

During the first quarter of 2017 no outfalls discharged.

If you have any questions feel free to contact me. (303) 866-3567 ext 8134

Sincerely,

Jason Musick  
Environmental Protection Specialist  
Jason.musick@state.co.us

