



STATE OF  
COLORADO

Cunningham - DNR, Michael <michaela.cunningham@state.co.us>

---

## COMPLAINT Gloria Z Mine M1984094

1 message

---

rrindsig@mchsi.com <rindsig@mchsi.com>

Mon, May 8, 2017 at 10:31 AM

To: "Cunningham - DNR, Michael" <michaela.cunningham@state.co.us>

Mr. Cunningham,

I have confirmed with Sarah Brucker of DWR (Denver) that the Gloria Z mine M1984094 at Fairplay has no current or approved SWSP, and has not had one since 2014.

This mine has exposed groundwater.

I understand that operation without an approved SWSP and exposed groundwater should result in immediate cessation of excavation below water level and cessation of use of any water at the mine.

I trust that if DRMS is responsible for halting operations at this mine due to the above, you will do so immediately.

Regards,  
Robin Rindsig