

COLORADO Division of Reclamation, Mining and Safety Department of Natural Resources

1313 Sherman Street, Room 215 Denver, CO 80203

May 29, 2017

Mr. Jack Henris Cripple Creek & Victor Gold Mining Company 100 N. Third Street P.O. Box 191 Victor, CO 80860

Re: Project, Permit No. M-1980-244; Technical Revision (TR-89) Third Adequacy Review

Dear Mr. Henris:

On June 9, 2017 the Division of Reclamation, Mining and Safety (Division) received your responses to our Second Adequacy Review (SAR) letter for Technical Revision (TR-89).

The following comments are based on the Division's review of CC&V's responses to the Division's SAR:

Part I The responses to the six issues identified in the April 7, 2017 PAR (Part I) are adequate.

General Comments.

- A) The High Grade Mill previously adequate response.
- B) Additional flotation tanks previously adequate response.
- C) List of other permits previously adequate response.

Comments Specific to the Submittal.

- D) Concentrate Stockpile Clarification The June 9, 2017 response is adequate.
- E) Hazardous Material Discussion: previously adequate response
- F) Secondary Containment for the Breezeway (p. 2, 6th paragraph) The June 9, 2017 response is adequate.
- G) Pad Extension (p. 3, 2nd paragraph). Please provide the following:
 - i. A complete set of current specifications... <u>The June 9, 2017 response is not adequate</u>. The specifications provided have a "DRAFT" watermark and are not acceptable as they would be expected to change prior to construction. Review of DRAFT specifications by the Division would be pointless. Again, please provide a complete set of <u>current</u> **final** specifications intended for the pad extension signed by a professional engineer licensed in Colorado



Mr. Jack Henris June 21, 2017 – TR-89 3AR Page 2

- ii. Rationale for why three different slopes are proposed. The June 9, 2017 response is adequate.
- iii. Discussion on whether or not additional liner is required. Previously adequate response.

Drawings.

- H) Drawing 20-647-001A. Previously adequate response.
- I) Drawing 20-647-002A. Previously adequate response.

Nonagglomerated Tailings Strength Assessment and Stability Evaluation.

- J) The Technical Memorandum (TM) prepared by NewFields:
 - i. A realistic assessment of the worst case ratio of tailings to ore The June 9, 2017 response is adequate.
 - ii. A written commitment to follow NewFields' recommendation in Section 4.0 Previously adequate response.

Supplemental Strength Assessment and Stability Evaluation Technical Memorandum.

K) The Technical Memorandum (TM) prepared by NewFields (dated March 8, 2017):

- i. Revisions to achieve the required Factors of Safety and addressing the comments in Item L below. Previously adequate response.
- ii. Requested specifications in Item G(i). <u>The response is not adequate</u>, see Item G(i) above.
- L) Slope stability analyses (Attachment A). Please revise the analyses to include the following:
 - i. Section A previously adequate response,
 - ii. Section B previously adequate response.

Additional Comments.

M) Attachment 5, Drawing 20-647-84. The June 9, 2017 response is adequate.

If you have any questions or need further information, please contact me at (303)866-3567 x8169.

Sincerely,

hing U

Timothy A. Cazier, P.E. Environmental Protection Specialist

ec: Wally Erickson, DRMS Amy Eschberger, DRMS Elliott Russell, DRMS DRMS file Meg Burt, CC&V