



*"Safety as a Value"*

Telephone: 970.385.4528  
Facsimile: 970.385.4638

GCC Energy, LLC  
6473 County Road 120  
Hesperus, CO 81326

October 4, 2017

State of Colorado  
Division of Reclamation, Mining & Safety  
1313 Sherman St, Suite 215  
Denver, CO 80203

Attention: Rob Zuber, Environmental Protection Specialist II

Re: 3rd Quarter 2017 Surface Subsidence Inspections  
3rd Quarter 2017 Huntington Ditch Inspections

Mr. Zuber:

Mike and Marc Crawford, of the Crawford Ranch property informed us that they continue to monitor subsidence cracks on their property. No new cracks have been located this quarter. They have informed us that all cracks on the Crawford Ranch property are minor; they will inform us if they feel action is required.

No subsidence issues have been noticed in the mined out areas west of Pine Gulch on the Huntington ranch property. Dan Huntington has not mentioned any subsidence related issues on other areas of his property.

Please call Tom Bird at (970) 385-4528 x 6503 if you have any questions or comments.

Sincerely,

A handwritten signature in black ink, appearing to read 'Tom Bird', with a large, stylized loop at the end.

Tom Bird  
Manager, Coal Services  
GCC Energy, LLC