

STATE OF
COLORADO

Cazier - DNR, Tim <tim.cazier@state.co.us>

Holcim Portland Plant Mining Inspection (Permit #M-1977-344)

1 message

Derrick Dease <derrick.dease@lafargeholcim.com>

Mon, Nov 13, 2017 at 2:26 PM

To: tim.cazier@state.co.us

Mr. Cazier,

I'm the Environmental Manager at the Holcim Portland Plant in Florence. Back in April, you performed a mine inspection with Dominic Bellino, our quarry supervisor. In your inspection report, you noted a couple of items and our plant manager asked me to reach out to you for clarification.

First, you mention that the plant had no current SWSP for the quarry. The plant's SWSP for CY2017 was submitted in November 2016 but was not approved until August 2017 (see attached approval letter) and covers CY2017. This letter should satisfy the lack of a SWSP finding noted in your report.

Second, you noted that the plant lacks a utilities structure agreement with, Kinder Morgan, the owner of the natural gas pipeline. To date, we have been unsuccessful in securing a letter/agreement with Kinder Morgan. Assuming we are unable to get a notarized letter from them, what are the legal/regulatory implications of this with regards to the plant's mining plan? Is there anything that can be done to rectify this finding in lieu of a direct letter from Kinder Morgan, in case we're not able to get it by your deadline.

Regards,
Derrick Dease

Derrick Dease
Area Environmental & Public Affairs Manager
Holcim (US) Inc., a member of LafargeHolcim Ltd.
3500 State Highway 120
Florence, CO 81226

Office: 719.288.1423
Mobile: [719.285.5762](tel:719.285.5762)
Fax: [719.784.4815](tel:719.784.4815)
Email: derrick.dease@lafargeholcim.com
www.lafargeholcim.com

This email is confidential and intended only for the use of the above named addressee(s). If you have received this e-mail in error, please delete it and notify me by e-mail or telephone.



Holcim Quarry SWSP 2017 FINAL - Approved.pdf

4818K