



COLORADO

Division of Reclamation,
Mining and Safety

Department of Natural Resources

1313 Sherman Street, Room 215
Denver, Colorado 80203

February 21, 2018

Tom Brubaker
Valco, Inc.
9296 Windhaven Dr.
Parker, CO 81034

Re: Lamar West Pit, Permit No. M-1981-132, Receipt of Corrective Action Documentation

Mr. Brubaker:

On February 19, 2018, the Division of Reclamation, Mining, and Safety (Division) received your Corrective Action Documentation for the problem identified during the inspection conducted at the Lamar West Pit on November 27, 2017. The status of the Corrective Action associated with this problem is as follows:

Corrective Action Documentation: The operator submitted photographic evidence showing the pit was backfilled to more than two feet above the groundwater surface.

Corrective Action Status: The Division considers the problem to be abated.

If you have any questions, please contact me by telephone at 303-866-3567, ext. 8129, or by email at amy.eschberger@state.co.us.

Sincerely,

Amy Eschberger
Environmental Protection Specialist

EC: Wally Erickson, DRMS at: wally.erickson@state.co.us

