

United Companies
15 Road Pit
1505 U.S. Hwy. 50
Fruita, CO.
DRMS Permit: M-2002-114
Annual Report Sketch

World Wide
Rental Services Yard

Xcel Energy
Substation

Fuel Station/
Secondary Containment

Truck Scales

Raining Classroom

Haul Road

Natural Fines

Future
Mining Area 5

Future
Mining Area 4

Future
Mining Area 3

Stockpiles

Int'l. Ditch

Berm

Wash Ponds

Dewatering Trench

Mining Direction

Crushing
Stockpiling Area

Mining Area 1 Lake

Parshall Flume

Sump/Pump

Berm

Permit Boundary

Top Soil Berm

Wetlands

Lake

Sloped Shoreline

Lake

Int'l. Ditch

Permit Boundary

Weed Management

Species: Canada thistle, Hoary Cress,

Russian Knapweed, Bareground

Herbicide: Chaparal @ 3.3oz/ac.

Journey @ 3.2oz/ac.

Throttle @ 12.5oz/ac.

16 Rd

Fruita Inlet

Interstate 70

Berm

Interstate 70

40' Concrete Ditch

Colorado River
State Channel