Figure 7. Logan Wash Mine Evaporation Pond Leak Detection Vault Water Levels Water level rising, pumping 5 & subsequent float switch Water level rising due to pump battery failure malfunction Pump float switch failure 3 Vault Pumped Vault taking on & Depth (ft) out; replaced pumping water existing pump Vault taking on & 2 pumping water Intermittent Pumping 1 Water level quasi-static 0 Water level quasi-static Vault manually pumped out Heads during download Date