

April 27, 2018

Mr. Peter Hays Division of Reclamation, Mining and Safety 1313 Sherman Street, Room 215 Denver, CO 80203

RE: Parsons Mine, M-2009-082, Follow-up to inspection dated April 3, 2018

Dear Mr. Hays:

The following is the status of the remaining outstanding items on the inspection report:

CORRECTIVE ACTIONS: The Operator shall provide the Division with a copy of the ditch relocation agreement by the corrective action date.

RESPONSE: Please find copy of agreement attached.

CORRECTIVE ACTIONS: The Operator shall, at the entrance of the mine site, post a sign which shall be clearly visible from the access road. The operator shall submit photo documentation that a proper sign has been posted by the corrective action date.

RESPONSE: Please find photo attached showing the sign has been re-attached to the fence at the entrance. We found it along the northeast property line. It must have blown off.

Please let me know if anything additional is needed.

Sincerely,

Julie Mikules

Julie Mikulas Regional Land Manager

Rocky Mountain Division – Northern Office 1800 N Taft Hill Road, Fort Collins, CO 80534 julie.mikulas@martinmarietta.com www.martinmarietta.com Mr. Peter Hays April 27, 2018 Page 2

