



STATE OF
COLORADO

Cazier - DNR, Tim <tim.cazier@state.co.us>

FW: M-1997-064 March Inspection Report - Updates

1 message

Joseph Joshua <jjoshua@gcc.com>

Mon, Apr 30, 2018 at 9:57 AM

To: "Cazier - DNR, Tim" <tim.cazier@state.co.us>

Cc: "phillip.courtney@state.co.us" <phillip.courtney@state.co.us>, Olivares Edwin <eolivares@gcc.com>

Tim,



Good Morning! I uploaded the Authorized Boundary for Disturbed Area of Salt Canyon Mine (you sent me) into our GPS, and we went out to stake it, as shown in the pictures, **the piles are within the Authorized Boundary**. Also, the below pics of GPS points of the Pile's Perimeter and the Authorized Boundary indicates that the pile is within the Authorized Boundary. Please kindly reverse the citation in this report.

The truck is on the boundary that's how far it is the pile is away









https://mail.google.com/mail/u/0/?ui=2&ik=5f09c8c280&jsver=GAFHaMvshdw.en.&cbl=gmail_fe_180506.06_p7&view=pt&as_from=jjoshua%40gcc.com&as_sizeoper

Joseph Joshua "JJ"

Cell: 719-568-3099

Off: 719-647-6820

From: Cazier - DNR, Tim <tim.cazier@state.co.us>
Sent: Thursday, April 5, 2018 3:53 PM
To: Joseph Joshua <jjoshua@gcc.com>
Cc: Phillip Courtney <phillip.courtney@state.co.us>
Subject: M-1997-064 March Inspection Report

Joseph,

A hard copy of the attached pdf file will be sent with tomorrow's mail. to Edwin Olivares. I've copied Phil Courtney (State Land Board) as State land is involved.

Please contact me if you have any questions.

Tim Cazier, P.E.

Environmental Protection Specialist

P 303.866.3567 x8169 | F 303.832.8106 | C 303.328.5229

1313 Sherman St., Room 215, Denver, CO 80203

tim.cazier@state.co.us | www.mining.state.co.us

5 attachments



IMG_0123.jpg
158K

IMG_0124.jpg
156K



IMG_0130.jpg
130K



INSP-REPORT_MWP_M-97-064_2018-03-28wEncl.pdf
2275K



Salt Canyon Project.kmz
224K