



Transit Mix Concrete Co.

444 E. Costilla Street, Colorado Springs, CO 80903 Office: (719) 475-0700 Fax: (719) 475-0226

June 8, 2018

Division of Reclamation, Mining and Safety
Attention: Mr. Tim Cazier
1313 Sherman St. Rm 215
Denver, CO 80203

RE: Response to the March 28, 2018 inspection report, Canon Dolomite Quarry, M1977-376

Dear Mr. Cazier,

Thank you for providing us a copy of the March 28, 2018 inspection report. We have several items which may need corrected or commented on:

- Under "Availability of Records", the inspection report states the, "Annual fees are paid through September 2017". Should this be September 2018?
- We are looking into our statement that the site lease or contract has made the landscape company aware of the permit conditions. We will ensure the contractor is aware of the permit conditions. We have developed a summary of the approved mining and reclamation plans and will provide those to the on-site contractor.
- We understand that for the broken concrete to be disposed on-site, the rebar must be cut away. As a point of clarification, does this mean only exposed rebar must be cut off the blocks of concrete or that the rebar must be broken free of the concrete?
- Under "Revegetation", the report states, "No revegetation efforts had been initiated." We would like to point out that the upper most benches of the Quarry site have been revegetated. The total area which has been revegetated is about .6 acres. The area has not been released, however.
- Under "Sediment Control", the report states, "The plan is to terrace this slope with likely three terraces having a back slope to convey the runoff towards the side into the natural drainage." We have refined the proposed design to include only one draining ditch with discharge structures that will be field fit and armored as necessary. In addition, the top of the slope, a diversion berm will be installed to prevent runoff from flowing over the crest of the slope. We have submitted a Technical Revision (TR), dated June 5, 2018, which addresses the New Fines Disposal Area. The TR also includes a site specific and revised seed mix which we have developed to better fit site soils and climatic conditions.

Please contact me if you have any questions.

Respectfully,

Brandon Hesper
Aggregate Production Manager
Transit Mix Concrete Co.



STATE OF
COLORADO

Cazier - DNR, Tim <tim.cazier@state.co.us>

Response to Canon Dolomite Quarry Inspection report from March 28, 2018 inspection

1 message

Brandon Heser <Brandon_Heser@transitmix.com>

Fri, Jun 8, 2018 at 11:40 AM

To: "Cazier - DNR, Tim" <tim.cazier@state.co.us>

Cc: bruce humphries <hlhumphries2@comcast.net>, Andre Laroche <Andre_Laroche@transitmix.com>

Tim,

I have attached a response to the inspection report that you sent for the March 28, 2018 inspection at the Canon Dolomite Quarry. I realize that there were no corrective actions cited, however there are just a couple of questions and points of clarification in this document. Please address our questions and request for clarification and let me know if you have any further questions of your own.

Thank you,

Brandon Heser

Aggregates Production Manager

Transit Mix Concrete Co.

Brandon_Heser@transitmix.com

Office: (719) 227-2080

Cell: (719) 313-0316



6-8-2018 Response to 3-28-18 Canon Dolomite Inspection Report.pdf

327K