Minerals Reclamation Permit Annual Report



Disclaimer

Under the terms of your NOI or Reclamation Permit and Colorado Statutes, you must submit Annual Fees and Annual Reports (including a map). You must pay the Annual Fee and submit an Annual Report each year until reclamation responsibility release is granted. The Annual Fee is not a renewal fee. The Fee and Report are for LAST YEAR'S mining and reclamation season, and MUST be paid even if your operation was inactive.

If you have requested reclamation responsibility release from the Division of Reclamation, Mining and Safety ("Division") but your permit is not released by the anniversary date listed below, the Annual Fee MUST be paid. If the permit is released before the anniversary date, then by Statute, it is not necessary to pay an Annual Fee or submit an Annual Report for that year.

Division records indicate the following is due:

Select Permit Number *

Only Permit Numbers with currently due Annual Fees will be listed. If the Permit Number is not listed, then the Annual Fees are not due, the Permit Number has already been submitted, or the Permit Number Annual Fee payment has been processed.

M2013070

Select Anniversary Date *

10-01-2018

PLEASE REMEMBER TO CLICK "SUBMIT" AFTER YOU HAVE COMPLETED YOUR REPORT AND PAYMENT.

Please check the box indicating you have read and understand the terms of the Annual Report and Annual Fee $^{\mbox{*}}$

▼ I understand and agree to the terms

General Information

Permittee Name

Liberty Mining, LLC

Operation Name

Liberty Mine

Permit Number Fee Due Permit Acreage

M2013070 518.00 9.90

County Anniversary Date Current Bond Amount

Mesa 10-01-2018 93862.42

Permittee Contact Information

Permitting Contact Name

Michael Shumway

Company Liberty Mining, LLC		
Address 1 1300 South Highway	<i>,</i> 191	
Address 2		
P.O. Box 1032		
City	State	Zip Code
Moab	UΤ	845320000
Phone #	Fax #	
4352592333	435259	9864
Permitting Contac		
rr.u308@frontier.co		
_	Contact information list in the contact in the cont	sted above correct? If it is not correct your organization's
• Yes • No	receive an email noti	neation.
Annual Rep	ort Questions	
compliance inspection	of the site. If, while comp	and will be reviewed by the Division upon receipt and prior to the next oleting this report, you learn that your site is not in compliance with the rules and promptly to avoid possible enforcement action.
1. Is the site iden	tification sign posted i	in accordance with Rule 3.1.12(1). *
• Yes • No		
2. Is the affected	area boundary clearly	marked in accordance with Rule 3.1.12(2).*
• Yes • No	area boundary elearly	
2 To the mine city	in final reclamation (all material extraction and stockpile removal is complete)? *
	_	etion of reclamation, Rule 3.1.3.
O Yes ⊙ No		
4. Has excavation	n, processing or haulin	g activity commenced at the site? *
O Yes O No	., processing or maumi	g detivity commenced at the site.
	operate more than 18	0 days per year? *
	Rule 1.13 to assure that yo	
O Yes O No	22220 4.46 70	
6. Has this mine l	peen granted approval	of TEMPORARY CESSATION Status? *
O Yes ⊙ No	3. a a a b b . 0 a a	

For the following questions, please note that numeric values must include one decimal place, such as "0.0" for zero acres, or 10.2 instead of 10.23.

7. Has this mine been granted approval for INTERMITTENT OPERATION? *

C Yes © No

8. Number of acres currently affected (mining + incomplete and or unreleased reclamation). * (?) 0.0
9. Number of acres that were newly affected during the current report year * (?) 0.0
10. Number of acres that were reclaimed during the current report year. * (?)0.0
11. Estimated new acreage to be affected in the next report year. * (?) 0.0
12. Estimated acres to be reclaimed in the next report year. * (?) 0.0
13. Total acres in various stages of reclamation, since permitted mining activities began:
Total acres backfilled * (?) 0.0
Total acres graded * (?) 0.0
Total acres seeded with approved mix * (?) 0.0
Seed Application Method * NA
Total acres fertilized with aproved fertilizer * (?) 0.0
Fertilizer Application Method * NA
Total acres with topsoil replaced * (?) 0.0
Topsoil replacement depth (in.) * (?) 0.0
Total acres mulched with approved mulch * (?) 0.0
Mulch application rate (tons/ac) * (?) 0.0
Mulch Application Method * NA
14. Is weed control being conducted in accordance with an approved Weed Control Plan? * If "YES", indicate the weed species, control area, control type, application rate and treatment date on the report map. C Yes C No N/A
15. Is adequate topsoil reserved for reclamation, based on your approved permit? * If "NO", please explain O Yes • No O N/A

16. Is the reserved topsoil vegetated/stabilized in accordance with Rule 3.1.9(1)? *
If "NO", please explain
C Yes C No ⊙ N/A
17. If mining has exposed groundwater, is the site in compliance with the approved mining plan and Office of the State Engineer (Well Permit, S.W.S.P., and/or Permanent Augmentation Plan)? ★ C Yes C No O N/A
18. Are all hazardous materials stored within approved spill containment structures? * C Yes C No ⊙ N/A
19. Is your financial warranty value sufficient to cover the cost to complete reclamation? * © Yes © No © N/A
20. Is your basis for legal right to enter still valid? * © Yes © No
21. Does your permit require you to submit monitoring information annually? ★ C Yes ⊙ No O N/A
22. As required by Colorado Mined Land Reclamation Act and/or Colorado Land Reclamation Act for the Extraction of Construction Materials (C.R.S.34-32-116 or 34-32.5-116), attach a map to this report that accurately depicts the permit boundary, current affected area boundary and location of the acreages specified in items 8-12 and 15. *
Only PDF formatted files can be uploaded.
Liberty Mine Map.pdf 83.95KB
23. If you have supplemental information you would like to provide, please upload it here.
Only PDF formatted files can be uploaded.
24. Rule 5.7 requires submittal of final abandonment reports within 60 days for any drill hole(s) with artesian flows and no later than 12 months for all other completed drill holes. If drill holes are a component of your exploration/prospecting activities, have they been properly abandoned? C Yes C No C NA
Annual Fee Payment
Payment Confirmation Number * (?)

No mining activity yet. Topsoil will be reserved as the site prep and mining activity begins. A topsoil stockpile

of approximately 200 cubic yards does exist from previous/historical mining activity.

Submittal Date

Signature

10-03-2018

Comment *
500 Characters MAX

I, the undersigned, hereby state that the information provided in this report is true and accurate, and that site operations are being conducted in accordance with the Division approved mining and reclamation plans. *

✓ I Agree

If you do not see the "Submit" button after completing your report, try to un-check and then re-check the "I Agree" box.