

October 17, 2018

Mr. Peter Hays Division of Reclamation, Mining and Safety 1313 Sherman Street, Room 215 Denver, CO 80203

RE: Iverson Mine M-2011-001, Follow-up to inspection dated August 10, 2018

Dear Mr. Hays:

Please accept this letter as our written response to the two items due 10/17/18.

1) CORRECTIVE ACTIONS: Backfill areas of settling near the inlet and outlet structures

RESPONSE: We have met with our contractor and there are still a few areas that need to be filled back in. This should occur before the end of the month, assuming we don't get any additional snow.

Please accept this letter as our written request to extend the due date for this problem from 10/17/18 to 11/17/18.

2) CORRECTIVE ACTIONS: Submit proof of the Tamarisk treatment by the corrective action date.

RESPONSE: We spent 2 days in September removing the Tamarisk from the shoreline around the lake before the property was re-seeded, crimped and mulched. Pictures are attached as proof of the removal.

Please let me know if anything additional is needed at this time (970) 407-3631.

Sincerely,

Jule Mikulas

Julie Mikulas Regional Land Manager

Rocky Mountain Division – Northern Office 1800 N Taft Hill Road, Fort Collins, CO 80534 julie.mikulas@martinmarietta.com www.martinmarietta.com

Tamarisk Removed 2018



