

1313 Sherman Street, Room 215 Denver, CO 80203

MEMO TO FILE

Date: <u>11/19/2018</u>	-	
Specialist: T. Cazier	Signed:	
1		

Subject/Operator/Operation/File No. <u>Notification of HGM process ore thickener overflow tank</u> primary containment spill

Type of Interaction:	Meeting	Phone Email Other	
Person(s) contacted a	nd affiliation:	Justin Bills (CC&V)	

Summary and Resolution of Interaction:

Mr. Bills emailed at 5:04 pm on 11/18/2018 (Sunday) to inform the Division that approximately 300 gallons of process water was released outside primary containment on the east side of the High Grade Mill (HGM) building, Saturday (9/29) at approximately 12:30 am. The spill was the result of an error of the level indicator of the process ore thickener overflow tank. CC&V reported the area where the process solution spilled outside of primary containment was over-excavated and impacted material was placed back on the mill feed stockpile. A sample of the material was collected and will be sent to the lab for analysis. Once received, CC&V will provide the results to DRMS.

CC&V intends to provide the required follow-up notice pursuant to Rule 8.2.3.

ec: Michael Cunningham, Elliott Russell, Amy Eschberger (DRMS)





Cazier - DNR, Tim <tim.cazier@state.co.us>

11/18/18 HGM Spill

1 message

Justin Bills <Justin.Bills@newmont.com> To: "Cazier - DNR, Tim" <tim.cazier@state.co.us> Cc: Tim Leedy <Tim.Leedy@newmont.com>, Meg Burt <Margaret.Burt@newmont.com>, Linda White <Linda.White@newmont.com>

Tim,

At approximately 12:30 am this morning, an error of the level indicator of the process ore thickener overflow tank, caused approximately 300 gallons of process water to exit primary containment. The area will be over-excavated and impacted material brought to the mill-feed stockpile. A sample of the material will be collected and sent to the lab for analysis. Once received, CC&V will provide the results to DRMS.

This email is to provide initial notice of the spill, a written notification will be provided within 5 days in accordance with Rule 8. Please contact me with any questions you may have.



Justin Bills

Senior Environmental Specialist

Cripple Creek and Victor Gold Mining Co.

T 719.689.4046

M 719.306.3388

www.newmont.com

Newmont Mining Corporation Cripple Creek and Victor Gold Mining Co.

100 North 3rd Street

Victor, CO 80860

Please consider the environment before printing this e-mail.