



## COLORADO

Division of Reclamation,  
Mining and Safety

Department of Natural Resources

1313 Sherman Street, Room 215  
Denver, CO 80203

December 27, 2018

Mr. John P. Ary  
Fremont Paving & Redi-Mix, Inc.  
P.O. Box 165  
Cañon City, CO 81215

**RE: Florence South Pit, File No. M-1988-093;  
Resolved Corrective Actions**

Dear Mr. Ary:

The Division of Reclamation, Mining and Safety (Division) has determined that the Corrective Actions assigned as a result of the June 14, 2018 inspection have been resolved. The following summarizes the problems identified, documentation received and date resolved:

Problem/Possible Violation	Corrective Action Documentation	Resolution Date
When an Operator temporarily ceases production of the mining operation for 180 days or more, the Operator must file a Notice of Temporary Cessation in writing to the Office	Notice of product being moved offsite received on November 20, 2018.	November 20, 2018
Tamarisk (salt cedar) trees present within the permit area.	Letter documenting tamarisk removal sent December 19, 2018 via email.	December 19, 2018
West side affected area boundary markers are missing.	Letter documenting placement of boundary markers sent December 19, 2018 via email.	December 19, 2018

If you have any questions, please contact me (303-866-3567 ext. 8169).

Sincerely,

Timothy A. Cazier, P.E.  
Environmental Protection Specialist

ec: DRMS file  
Jodi Schreiber

