# **Minerals Reclamation Permit Annual Report**



## **Disclaimer**

Under the terms of your NOI or Reclamation Permit and Colorado Statutes, you must submit Annual Fees and Annual Reports (including a map). You must pay the Annual Fee and submit an Annual Report each year until reclamation responsibility release is granted. The Annual Fee is not a renewal fee. The Fee and Report are for LAST YEAR'S mining and reclamation season, and MUST be paid even if your operation was inactive.

If you have requested reclamation responsibility release from the Division of Reclamation, Mining and Safety ("Division") but your permit is not released by the anniversary date listed below, the Annual Fee MUST be paid. If the permit is released before the anniversary date, then by Statute, it is not necessary to pay an Annual Fee or submit an Annual Report for that year.

Division records indicate the following is due:

#### Select Permit Number \*

Only Permit Numbers with currently due Annual Fees will be listed. If the Permit Number is not listed, then the Annual Fees are not due, the Permit Number has already been submitted, or the Permit Number Annual Fee payment has been processed.

M2012050

### Select Anniversary Date \*

01-24-2019

#### PLEASE REMEMBER TO CLICK "SUBMIT" AFTER YOU HAVE COMPLETED YOUR REPORT AND PAYMENT.

Please check the box indicating you have read and understand the terms of the Annual Report and Annual Fee  $^{\mbox{*}}$ 

▼ I understand and agree to the terms

### **General Information**

#### **Permittee Name**

Oldcastle SW Group, Inc. dba United Companies of Mesa County

### **Operation Name**

Otter Creek Pit

Permit Number	Fee Due	Permit Acreage
---------------	---------	----------------

M2012050 791.00 89.20

County Anniversary Date Current Bond Amount

Mesa 01-24-2019 124375.61

## **Permittee Contact Information**

#### **Permitting Contact Name**

Jason Burkey

Company		
Oldcastle SW Group, I County	nc. dba United Compan	ies of Mesa
Address 1		
2273 River Road		
Address 2		
City	State	Zip Code
Grand Junction	СО	815020000
Dhana #	Fax #	
Phone #	Fax #	
9702434900	970243	5945
Permitting Contact	Email Address	
jason.burkey@oldcast	lematerials.com	
Is the Permitting Co	ontact information lis	sted above correct? If it is not correct your organization's
Administrator will re	eceive an email notif	fication. *
• Yes • No		
Annual Bono	rt Ouestiens	
Annual Repo	rt Questions	
Information contained in compliance inspection of	this report is required an	
Information contained in compliance inspection of the act, it is advisable the	this report is required an f the site. If, while comp at the issues be rectified	leting this report, you learn that your site is not in compliance with the rules an promptly to avoid possible enforcement action.
Information contained in compliance inspection of the act, it is advisable the site identif	this report is required an f the site. If, while comp at the issues be rectified	leting this report, you learn that your site is not in compliance with the rules an
Information contained in compliance inspection of the act, it is advisable the site identif	this report is required an f the site. If, while comp at the issues be rectified	leting this report, you learn that your site is not in compliance with the rules an promptly to avoid possible enforcement action.
Information contained in compliance inspection of the act, it is advisable the act, it is advisable the site identiform Yes © No	this report is required an f the site. If, while comp at the issues be rectified	leting this report, you learn that your site is not in compliance with the rules an promptly to avoid possible enforcement action.
Information contained in compliance inspection of the act, it is advisable the act, it is advisable the site identifulation of Yes O No  2. Is the affected as	this report is required an f the site. If, while comp at the issues be rectified	leting this report, you learn that your site is not in compliance with the rules an promptly to avoid possible enforcement action.  n accordance with Rule 3.1.12(1).*
Information contained in compliance inspection of the act, it is advisable the act, it is advisable the act, it is advisable the site identifulation of Yes C No  2. Is the affected and Yes C No	this report is required and the site. If, while compart the issues be rectified at the issues be rectified in the issues because the interest in the issues because the interest in the interest	leting this report, you learn that your site is not in compliance with the rules an promptly to avoid possible enforcement action.  n accordance with Rule 3.1.12(1).*
Information contained in compliance inspection of the act, it is advisable the act, it is advisable the site identifulation of Yes O No  2. Is the affected and Yes O No  3. Is the mine site in	this report is required and the site. If, while compart the issues be rectified at the issues because the interest at the issues because the interest at th	leting this report, you learn that your site is not in compliance with the rules an promptly to avoid possible enforcement action.  n accordance with Rule 3.1.12(1). *  marked in accordance with Rule 3.1.12(2). *
Information contained in compliance inspection of the act, it is advisable to act	this report is required and the site. If, while compart the issues be rectified at the issues because the interest at the issues because the interest at th	leting this report, you learn that your site is not in compliance with the rules an promptly to avoid possible enforcement action.  n accordance with Rule 3.1.12(1). *  marked in accordance with Rule 3.1.12(2). *  all material extraction and stockpile removal is complete)? *
Information contained in compliance inspection of the act, it is advisable to Yes O No  3. Is the mine site in act in Yes," please note time O Yes O No	this report is required and the site. If, while compart the issues be rectified at the issues because at the	leting this report, you learn that your site is not in compliance with the rules an promptly to avoid possible enforcement action.  n accordance with Rule 3.1.12(1). *  marked in accordance with Rule 3.1.12(2). *  all material extraction and stockpile removal is complete)? *  tion of reclamation, Rule 3.1.3.
Information contained in compliance inspection of the act, it is advisable to acc.  2. Is the affected and acc. Yes O No.  3. Is the mine site in acc. Yes O No.  4. Has excavation,	this report is required and the site. If, while compart the issues be rectified at the issues because at the	leting this report, you learn that your site is not in compliance with the rules an promptly to avoid possible enforcement action.  n accordance with Rule 3.1.12(1). *  marked in accordance with Rule 3.1.12(2). *  all material extraction and stockpile removal is complete)? *
Information contained in compliance inspection of the act, it is advisable to acc.  Is the affected and Yes O No  Is the mine site in Yes," please note time O Yes O No  4. Has excavation,  O Yes O No	this report is required and the site. If, while compart the issues be rectified at the issues between the issue	leting this report, you learn that your site is not in compliance with the rules an promptly to avoid possible enforcement action.  n accordance with Rule 3.1.12(1). *  marked in accordance with Rule 3.1.12(2). *  all material extraction and stockpile removal is complete)? *  tion of reclamation, Rule 3.1.3.  g activity commenced at the site? *
Information contained in compliance inspection of the act, it is advisable to Yes O No  3. Is the mine site in act in the act, it is advisable the act in th	this report is required and the site. If, while compart the issues be rectified at the issues between the issue	leting this report, you learn that your site is not in compliance with the rules an promptly to avoid possible enforcement action.  n accordance with Rule 3.1.12(1). *  marked in accordance with Rule 3.1.12(2). *  all material extraction and stockpile removal is complete)? *  tion of reclamation, Rule 3.1.3.
Information contained in compliance inspection of the act, it is advisable to the act, it is advisable to act, it is advisable	this report is required and the site. If, while compart the issues be rectified at the issues between the issue	leting this report, you learn that your site is not in compliance with the rules an promptly to avoid possible enforcement action.  n accordance with Rule 3.1.12(1). *  marked in accordance with Rule 3.1.12(2). *  all material extraction and stockpile removal is complete)? *  tion of reclamation, Rule 3.1.3.  g activity commenced at the site? *
Information contained in compliance inspection of the act, it is advisable to the act, it is advisable to the	this report is required and the site. If, while compart the issues be rectified at the issues between the issue	leting this report, you learn that your site is not in compliance with the rules an promptly to avoid possible enforcement action.  In accordance with Rule 3.1.12(1). *  I marked in accordance with Rule 3.1.12(2). *  all material extraction and stockpile removal is complete)? *  tion of reclamation, Rule 3.1.3.  I g activity commenced at the site? *  Processing or hauling activity at the mine? *
Information contained in compliance inspection of the act, it is advisable the act and act	this report is required and the site. If, while compart the issues be rectified part the issues be rectified processing or hauling of last excavation, processing or hauling or ha	leting this report, you learn that your site is not in compliance with the rules are promptly to avoid possible enforcement action.  In accordance with Rule 3.1.12(1). *  Imarked in accordance with Rule 3.1.12(2). *  all material extraction and stockpile removal is complete)? *  tion of reclamation, Rule 3.1.3.  In activity commenced at the site? *  In accordance with Rule 3.1.12(2). *
Information contained in compliance inspection of the act, it is advisable the act and act	this report is required and the site. If, while compate the issues be rectified at the issues between the issu	leting this report, you learn that your site is not in compliance with the rules an promptly to avoid possible enforcement action.  In accordance with Rule 3.1.12(1). *  Imarked in accordance with Rule 3.1.12(2). *  all material extraction and stockpile removal is complete)? *  tion of reclamation, Rule 3.1.3.  In activity commenced at the site? *  In activity commenced at the mine? *  In activity at the mine? *
Information contained in compliance inspection of the act, it is advisable to a second act, it is advisable the act, it is advisable to a second act, it	this report is required and the site. If, while compart the issues be rectified at the issues between the issues b	leting this report, you learn that your site is not in compliance with the rules an promptly to avoid possible enforcement action.  In accordance with Rule 3.1.12(1). *  Imarked in accordance with Rule 3.1.12(2). *  Call material extraction and stockpile removal is complete)? *  It tion of reclamation, Rule 3.1.3.  In activity commenced at the site? *  Corocessing or hauling activity at the mine? *  Corocessing or hauling activity at the mine? *

7. Has this mine been granted approval for INTERMITTENT OPERATION? \*

C Yes © No

zero acres, or 10.2 instead of 10.23.
8. Number of acres currently affected (mining + incomplete and or unreleased reclamation). * (?) 36.0
<ul><li>9. Number of acres that were newly affected during the current report year * (?)</li><li>1.0</li></ul>
<ul><li>10. Number of acres that were reclaimed during the current report year. * (?)</li><li>1.0</li></ul>
11. Estimated new acreage to be affected in the next report year. * (?) 0.0
12. Estimated acres to be reclaimed in the next report year. * (?) 0.0
13. Total acres in various stages of reclamation, since permitted mining activities began:
Total acres backfilled * (?) 1.0
Total acres graded * (?) 1.0
Total acres seeded with approved mix * (?) 0.0
Seed Application Method * NA
Total acres fertilized with aproved fertilizer * (?) 0.0
Fertilizer Application Method * NA
Total acres with topsoil replaced * (?) 0.0
Topsoil replacement depth (in.) * (?) 0.0
Total acres mulched with approved mulch * (?) 0.0
Mulch application rate (tons/ac) * (?) 0.0
Mulch Application Method * NA
14. Is weed control being conducted in accordance with an approved Weed Control Plan? *  If "YES", indicate the weed species, control area, control type, application rate and treatment date on the report map.  • Yes • No • N/A
15. Is adequate topsoil reserved for reclamation, based on your approved permit? *

For the following questions, please note that numeric values must include one decimal place, such as "0.0" for

⊙ Yes C No C N/A
16. Is the reserved topsoil vegetated/stabilized in accordance with Rule 3.1.9(1)? *  If "NO", please explain  O Yes O No O N/A
17. If mining has exposed groundwater, is the site in compliance with the approved mining plan and Office of the State Engineer (Well Permit, S.W.S.P., and/or Permanent Augmentation Plan)? *  © Yes © No © N/A
<b>18.</b> Are all hazardous materials stored within approved spill containment structures? <b>★</b> ⊙ Yes ○ No ○ N/A
19. Is your financial warranty value sufficient to cover the cost to complete reclamation? ★  ⊙ Yes C No C N/A
20. Is your basis for legal right to enter still valid? *  © Yes © No
21. Does your permit require you to submit monitoring information annually? ★ ○ Yes ○ No ○ N/A
22. As required by Colorado Mined Land Reclamation Act and/or Colorado Land Reclamation Act for the Extraction of Construction Materials (C.R.S.34-32-116 or 34-32.5-116), attach a map to this report that accurately depicts the permit boundary, current affected area boundary and location of the acreages specified in items 8-12 and 15. *
Only PDF formatted files can be uploaded.
M2012 050 Site Map.pdf 4.86MB
23. If you have supplemental information you would like to provide, please upload it here.
Only PDF formatted files can be uploaded.
24. Rule 5.7 requires submittal of final abandonment reports within 60 days for any drill hole(s) with artesian flows and no later than 12 months for all other completed drill holes. If drill holes are a component of your exploration/prospecting activities, have they been properly abandoned?
○ Yes ○ No ○ NA
Annual Fee Payment
Payment Confirmation Number * (?) 101202866
Signature
Signature
Submittal Date 01-15-2019

If "NO", please explain