

STATE OF
COLORADO

Zuber - DNR, Rob <rob.zuber@state.co.us>

Items related to New Elk ARR

1 message

Zuber - DNR, Rob <rob.zuber@state.co.us>
To: Nick Mason <nmason@newelkcoal.com>
Cc: Louis Head <lhead@newelkcoal.com>

Fri, Mar 8, 2019 at 9:59 AM

Hi, Nick

I am looking again at your ARR and have some more questions and comments on Table 3 and the map for the east side of your site (in addition to items in the letter I sent to NECC dated 27 February). Apologies if you answered any of these in the past, but I think most or all are new items.

1. On the map there is a parcel labeled "2" and one labeled "2, 3, & 4". What rows in Table 3 correspond to these? The acreage of 5.41 is too big, I think, to be just for the "2" area on the map.
2. For Area 6, Equipment Storage, the acreage appears too high. Please check.
3. Should Area 30 go away on the map and in the table? I do not think this topsoil pile exists.
4. Area 34 on the map is an odd one. The area is much bigger than the acreage in the table. Also, it implies NECC seeded the river.
5. Why no values in the B&G and topsoil columns in Table 3 for some of the RDA benches?
6. Area 1 should be listed with the West Portal facilities.
7. The polygon for Area 39 is not shown.
8. For Area 7, why no row for 1990?

One general comment about the map: if you remove topo (and maybe other layers) it would be less busy and easier to read.

Thanks for looking into these items.
Rob

Rob Zuber, P.E.
Environmental Protection Specialist II
Division of Reclamation, Mining and Safety - Coal Regulatory Program



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P 303.866.3567, extension 8113 | F 303.832.8106
1313 Sherman Street, Room 215, Denver, CO 80203
rob.zuber@state.co.us | <http://mining.state.co.us>