

August 12, 2019

Mr. Mike Schaffner Cripple Creek & Victor Gold Mining Company P. O. Box 191 Victor, CO 80860

Re: Cripple Creek & Victor Mining, Co., Cresson Project, M-1980-244; Acceptance of VLF 2 Phase 1 DCF Erosion Repair Construction Quality Assurance Report

Dear Mr. Schaffner:

The Division of Reclamation, Mining and Safety (DRMS) received via email your VLF 2 Phase 1 DCF Erosion Repair Construction Quality Assurance Report today. The DRMS has reviewed the report and has no comments.

The repair of the eroded drain cover Fill (DCF) on the northwest portion of the Phase 1 VLF 2 was determined to be in compliance with the approved specifications. The Certification is accepted by the DRMS pursuant to Rule 7.3.2 of the Mineral Rules and Regulations of The Colorado Mined Land Reclamation Board for Hard Rock, Metal, and Designated Mining Operations. CC&V may proceed with stacking ore in this repaired area.

If you have any questions or need further information, please contact me at (303)866-3567 x8169.

Sincerely,

Timothy A. Cazier, P.E. Environmental Protection Specialist

ec: Michael Cunningham, DRMS Patrick Lennberg, DRMS Elliott Russell, DRMS Justin Raglin, CC&V Justin Bills, CC&V DRMS file