

**1**: Stockpile Top Soil

SL/2 NW 1/4 OF SECTION 13, T6N R9W, 6th P.M., MOHAWT COUNTY, COLORADO



- NOTICE: ACCORDING TO COLORADO LAW, YOU MUST COMMENCE ANY LEGAL ACTION BASED ON ANY DEFECT IN THIS SURVEY WITHIN THREE YEARS AFTER YOU FIRST DISCOVER SUCH DEFECT. IN NO EVENT MAY ANY ACTION BE COMMENCED MORE THAN TEN YEARS FROM THE DATE OF CERTIFICATION SHOWN HEREON.

|  |   |
|--|---|
| DRYDEN & PEARCE CONSULTING<br>TEL: 011 961 7998 10   | MARTIN PILLA<br>EXPORT '02  |
| SINGAPORE OFFICE: 11, PARKVIEW, 604<br>(SINGAPORE TELEPHONE)   | DOWLING<br>LAND SURVEYORS<br>11, ROBINSON ROAD<br>HAYWARD 02 64 039<br>(970) 277-3613<br>FAX 276-4595 |
| NAME: _____<br>TITLE: _____<br>COMPANY: _____<br>ADDRESS: _____<br>CITY: _____<br>STATE: _____<br>ZIP: _____<br>COUNTRY: _____ |   |

MARVIN MOORE LS #9327

THIS MAP WAS DRAWN FROM INFORMATION ON GLO PLATS, TOPOGRAPHIC MAPS AND OTHER PUBLIC RECORDS, AND IT REPRESENTS THE TRUE FIELD CONDITIONS TO THE BEST OF MY KNOWLEDGE AND BELIEF.

SCALE: 1 MILE = 8.4 INCHES

RESIDENTIAL DEVELOPMENT 1 MILE NORTH  
OF THE AFFECTED AREA IS NOT A MUNICIPALITY.

LOCATION MAP

MARTIN PIT NO. 1-A  
APPLICANT : HEROWN ENTERPRISES

MARTIN PIT NO. 1-A

MARTIN PIT NO. 1-A  
APPLICANT: HEROWN ENTERPRISES

Reckward Ruth

Samuel Hays

Mr Ayer to be named

