

OXBOW MINING, LLC

3737 Hwy 133 P.O. Box 535 Somerset, Colorado 81434 USA Tel (970)929-5122 Fax
(970)929-5177



January 9, 2020

Mr. Leigh Simmons
Environmental Protection Specialist
Colorado Division of Reclamation, Mining and Safety
1313 Sherman Street, Room 215
Denver, CO 80203

Re: Oxbow Mining, LLC., Terror Creek Loadout, Permit C-1983-059
2019 Annual Hydrologic Report

Dear Mr. Simmons,

Please accept this letter as the 2019 Annual Hydrologic Report for the Oxbow Mining, LLC., Terror Creek Loadout. As the Division is aware, the facility has been dismantled and equipment removed from the site.

The sediment pond and dugout pond are both inspected at least quarterly. During 2018 no water discharges occurred. No water monitoring was performed or was required at the site.

Water is no longer used at the loadout facility for dust suppression or office use. The shower facility has been removed from service and was demolished and removed during 2019. The site has two sources of water, which were not used during 2019. There is a domestic well which supplied water for the office and showers and water from the Deer Trail Ditch was used for dust suppression of the loadout facility. There is no record kept of consumptive use during the year.

Please call me at 970-929-6034 if you have any questions.

Sincerely,

Doug A. Smith
Chief Engineer

Xc: Mike Ludlow (OMLLC)
files