



"Safety as a Value"

Telephone: 970.385.4528
Facsimile: 970.385.4638

GCC Energy, LLC
6473 County Road 120
Hesperus, CO 81326

June 16, 2020

State of Colorado
Division of Reclamation, Mining & Safety
1313 Sherman St, Suite 215
Denver, CO 80203

Attention: Janet Binns, Environmental Protection Specialist III

Re: 2nd Quarter 2020 Surface Subsidence Inspections
2nd Quarter 2020 Huntington Ditch Inspections

Ms. Binns:

Mike and Marc Crawford, of the Crawford Ranch property informed us that they continue to monitor subsidence cracks on their property. No new cracks have been located this quarter. They have informed us that all cracks on the Crawford Ranch property are minor; they will inform us if they feel action is required.

No subsidence issues have been noticed in the mined out areas west of Pine Gulch on the Huntington ranch property. Dan Huntington has not mentioned any subsidence related issues on other areas of his property.

Please call Tom Bird at (970) 385-4528 x 6503 if you have any questions or comments.

Sincerely,

A handwritten signature in black ink, appearing to read 'Tom Bird', with a large, stylized loop at the end.

Tom Bird
Manager, Coal Services
GCC Energy, LLC