Notes:

7. Approximately 14.78 acres was stripped (brown) and partially mined in 2020. The total disturbance at the mine is 38.93 acres ±. Mining continues on areas previously disturbed by working into area previously stripped (tan) and making the mine deeper.

9. Topsoil from the newly stripped area was stockpiles along the perimeter of the working area.

12. No reclamation is required at this time as mining has not reached the areas adjacent to the mine boundary.

19. Current Bond Amount \$60,500.00 and covers 40 acres of disturbance. Division reviewed the bond amount on 03/01/2017 when the mine was last inspected and determined is was adequate at that.