

Exhibit E page 1 of 2

1/4 Section Line

1/4 Section Line

Existing 2-Track Road

East 1/4 corner, Section 35
1186 Brass
Cap on a pile
of stones


Section Line

EXISTING DAM

MATERIAL STOCKPILE AND STAGING
AREA FOR TRUCKS FOR
LOADING, ACCESSED FROM AND NEXT
TO EXISTING ROAD.

320 CUBIC YARDS
OF TOPSOIL.

STOCKPILED &
FENCED WITH
'TOPSOIL' SIGN.



1/4 Section Line

Plan View of: Lost Cause Mine Plan

(NOT TO SCALE)

SUBJECT PARCEL & DESCRIPTION

Contains 6.182 acres more or less.

Beginning at a point in the SE 1/4 of Section 35, T2S, R9E, E4 P.M. which point bears N34deg43'32"E 148.87' from the South 1/4 corner of said section being a 1898 brass cap in a pile of stones; Thence N34deg43'45"E 1176.62'; Thence S18deg53'30"E 842.79'; Thence S45deg51'11"W 742.41'; Thence N44deg43'42"W 428.54' to the point of beginning. Basis of bearing is the line between the South 1/4 corner and the East 1/4 corner of Section 35, T2S, R9E, E4 P.M. which is taken from Global Positioning Satellite Observations to bear N34deg43'34"E a measured distance of 3782.87' (then East 1/4 corner being a 1898 brass cap in a pile of stones).