

**Regional Land Manager** 

September 21, 2020

Mr. Peter Hays Division of Reclamation, Mining and Safety 1313 Sherman Street, Room 215 Denver, CO 80203

RE: Iverson M-2011-001, Follow-up to inspection dated August 5, 2020

Dear Mr. Hays:

Please accept this letter as our written response to the item due 09/21/2020.

CORRECTIVE ACTIONS: The Division will require the Operator to remove the woody vegetation, treat the structures to prevent the establishment of woody vegetation in the spillways and provide evidence of the completed work.

RESPONSE: Documentation attached to show clearing of woody vegetation. Spillways were sprayed with the following herbicides:

- Roundup Max (glyphosate)
- Ecomazapyr (Imazapyr 27.8%)
- Tordon RTU for larger stumps

Please let me know if anything additional is needed at this time (970) 407-3631.

Sincerely,

Julie Mickulas

Julie Mikulas Regional Land Manager

Rocky Mountain Division – Northern Office 1800 N Taft Hill Road, Fort Collins, CO 80534 julie.mikulas@martinmarietta.com www.martinmarietta.com

## Iverson West Spillway







After

## Iverson East Spillway



Before

After