

Notes:

Please refer to the 2020 Annual Report Map for location of the areas of disturbance in the mine. We continued to remove material from stockpiles and the mined area. No reclamation is required at this time.

9. We continued to remove material for stockpiles and pull material from the working face this year. No new area was disturbed.

13 The oil company reseeded the slopes around the oil pad in 2019 after changing the shape of the pad. We are monitoring the work completed but they need to do additional seeding along the west side of the pad on the changed area.

14. Weed control was done on June 16-17, 2020 in accordance with the Garfield Weed Management Plan for the mine and spot work was done on the Plant Site areas and roadways. Escort and 2-4-D was applied to the Hoary Crest, and Kochia. Telar and Milestone were used on the Russian Knapweed. Ranger pro was use on grass areas to control the weeds in those areas. The spraying is successful in controlling the weeds and weed control will continue next year.

18 . The bond is currently set at \$20,408 for disturbance on the entire area. This mine was last inspected on 3/23/2017.