## 112c Annual Report

Permittee Name:	Aggregate Industries - WCR,Inc.	Permit Number:	M-1997-141
Operation Name:	Lyons Quarry	County:	Boulder
Annual Fee Due:	\$791.00	Anniversary Date:	December 29, 2018
Permit Acreage:	71.00	Current Bond Amt:	\$191,600.00

According to C.R.S. 34-32.5-116 or 34-32-116, each year, on the anniversary date of the permit, an operator shall submit the Annual Fee, an Annual Report and Map showing the extent of current disturbances to affected land, required monitoring information, reclamation accomplished to date and during the preceding year, any new disturbance that is anticipated to occur during the upcoming year, any reclamation that will be performed during the upcoming year, the dates for the beginning of active operations, and the date active operations ceased for the year, if any.

Information contained in this report will be reviewed by the Division upon receipt and prior to the next compliance inspection of the site. If, while completing this report, you learn that your site is not in compliance with the rules and the act, it is advisable that the issues be rectified promptly to avoid possible enforcement action.

1.	Is the site identification sign posted in accordance with Rule 3.1.12(1)	<u>YES</u>	NO
2.	Is the affected area boundary clearly marked in accordance with Rule 3.1.12(2)	<u>YES</u>	NO
3.	Is the mine site in final reclamation (all material extraction and stockpile removal is complete)? If "YES," please note time limits related to completion of reclamation, Rule 3.1.3.	<u>YES</u>	NO
4.	What was the date of last excavation, processing or hauling activity at the mine? 2009		
5.	Does the mine operate more than 180 days per year? If "NO", please review Rule 1.13 to assure that your mine is in compliance.	YES	<u>NO</u>
6.	Has this mine been granted: <ul><li>a) approval of TEMPORARY CESSATION Status?</li><li>b) approval for INTERMITTENT OPERATION?</li></ul>	YES YES	NO NO
7.	Number of acres currently affected (mining+ incomplete and or unreleased reclamation)	46 +/-	
8. 9.	Number of acres that were newly affected during the current report year. Number of acres that were reclaimed during the current report year.	<u>0</u> <u>0</u>	
	. Estimated new acreage to be affected in the next report year Estimated acres to be reclaimed in the next report year.	<u>0</u> <u>Undetern</u>	nined

12. **Total acres** in various stages of reclamation, since permitted mining activities began:

Total acres	Total act	res	Total acres		Total a	acres	
backfilled:	seeded v	w/	w/topsoil		mulche	ed w/	
	approve	d mix:	replaced:	approved mulch:			
Total acres graded:	Total acr fertilized apvd fer	w/	Topsoil replacement depth (in.):		Mulch rate (to	application ons):	
Seed application method:	·	Fertilizer application method:		Mulci applic metho	cation		

	the weed species, control area, control type, and control efforts are performed as needed		nent dat	te on th	ıe
	. Is adequate topsoil reserved for reclamation, based on your approved permit? If "NO", please explain: <i>Refer to TR-03 and TR-04</i>			NO	N/A
	5. Is the reserved topsoil vegetated/stabilized in accordance with Rule 3.1.9(1)? If "NO" please explain:			NO	N/A
	16. If mining has exposed groundwater, is the site in compliance with the approved mining State Engineer (Well Permit, S.W.S.P., and/or Permanent Augmentation Plan)?			d Office NO	of the N/A
17. Are all hazardous	17. Are all hazardous materials stored within approved spill containment structures?			NO	N/A
Additional \$540,	18. Is your financial warranty value sufficient to cover the cost to complete reclamation?  *Additional \$540,577.00 in financial warranty will be submitted on or before February 13.				
19. Is your basis for lo	egal right to enter is still valid?		<u>YES</u>	NO	
	20. Does your permit require you to submit monitoring information annually? If"Yes", please attach the required monitoring results to this annual report.			NO NO	N/A
Permittee Contact:	formation:  Jeremy Deuto, PE, PG				
Permittee Company:	Aggregate Industries-WCR, Inc.				
Address:	1687 Cole Blvd., Ste. 300				
	Golden, CO 80401				
Phone Number:					
Fax Number:					
Email Address:	Jeremy.deuto@lafargeholcim.com				
	reby state that, to the best of my knowledge, site operations are being conducted in acco				
W. Mundle					
W. Mun		12/16/2020			

Date

Signature of Corporate Officer, Owner, or Documented Designee

13. Is weed control being conducted in accordance with an approved Weed Control Plan? YES N/A