

Foidel Creek Mine 29515 RCR 27 Oak Creek, CO 80467

Twentymile Coal, LLC

970.879.3800

July 1, 2021

Ms. Tabetha Lynch, Environmental Protection Specialist Division of Reclamation, Mining, and Safety 1313 Sherman Street, Room 215 Denver, Colorado 80203 (303) 866-3567 X 8147

RE: Twentymile Coal, LLC - Foidel Creek Mine (Permit No. C-82-056), Technical Revision (TR21-96) Bond Reduction Revision, Adequacy #3b

Dear Ms. Lynch:

Twentymile Coal, LLC (TC) has received and reviewed the Adequacy review No. 3 items. TC is providing the additional response regarding the Task 1 Facilities PMT Map 31a Backfill and Regrade Boundaries:

- TC has decided to remove Task 1 from the TR96 revision.
 - Please remove Map 31A from this revision. TC may revisit Task 1 and the mine facilities PMT later with a new revision.

A new summary of revision and addition page is attached with this submittal as well as a table of the tasks effected by this revision.

Please do not hesitate to reach out to me if you have any further questions or need additional clarification.

Sincerely,

Miranda Kawcak

Miranda Kawcak Environmental Manager mkawcak@peabodyenergy.com 970-870-2718

cc: Sam Anderson (TC) Kyle Wagner (TC)

TWENTYMILE COAL COMPANY – FOIDEL CREEK MINE TECHNICAL REVISION TR21-96 BOND REDUCTION SUMMARY OF REVISIONS/ADDITIONS (revised 06/21)			
REVISION/ADDITION	DESCRIPTION	PLACEMENT INSTRUCTIONS	
TABLE OF CONTENTS	-		
XXV	List of Maps	Replaces Page XXV	
OPERATIONS PLAN – MINE FACILITIES (RULE 2.05)			
Pages 2.05-11.2, 18.1, 19, 30, 38, 45.22, 45.23, 45.24, and 47.1.	Revised operations and reclamation plan text incorporating information on omitted permitted items.	Replaces Pages 2.05-11.2, 18.1, 19, 30, 38, 45.22, 45.23, 45.24, and 47.1 in Volume I Remove Page 18.2 in Volume 1	
MAPS			
Map 23C (Base, Sheet ¼ and sheet 2/4) Surface Disturbance & Monitoring Map 24 (Sheet ¼ and Sheet ¾), Surface Facilities and Fresh Water Systems Map 29 (Sheet ¼ and Sheet ¾) Reclamation Map	Revised maps showing omitted buildings and minor changes reflected by TR96	Replaces Map 23C (base, sheet ¹ / ₄ , and sheet 2/4), Map 24 (Sheet ¹ / ₄ and ³ / ₄), Map 29 (Sheet ¹ / ₄ and Sheet ³ / ₄) in Volume V-A.	
EXHIBITS			
49Y 15Left Vent Shaft	Revised Drawings omitting the shaft and structures.	Replace F1 and F2 in Exhibit 49Y.	

Task	Description	Cost
37	Push Low Quality Coal into Pit	\$ 408,125.00
55	Remove Employee Coal Stockpile to Refuse Pile; MR274	\$ 532.00
184	Permanent Coal Fines Disposal From FCB Spill;MR297	\$ 533.00
181	15Left Shaft Seal	\$ 1,147.97
190	15Left Rock Dust Tank	\$ 957.60
190	15Left Rock Dust Tank Pad	\$ 41.05
190	15Left Rock Dust Tank Piers	\$ 1,024.40
190	15Left Shaft Concrete Pad	\$ 7,467.00
190	15Left Shaft Suface Casing	\$ 145.80
190	15Left Powerlines	\$ 16,970.35
190	15Left Fence	\$ 1,132.80
190	Demo Longwall Yard Storage Building Cassions	\$ 374.68
190	Demo Longwall Yard Storage Building	\$ 25,530.00
190	Refuse Bin Concrete Slab	\$ 4,851.25
190	Refuse Bin Cassion Supports	\$ 245.04

TR21-96 Bond Reduction Items