

Notes:

Please refer to the 2021 Annual Report Map for the location of the areas discussed below.

8. The following list outlined the various areas of disturbance at the mine

Description	Acres
Growth medium Piles 28,500 cyd	1.6 (cross hatched)
Stripped area	5.2 (tan)
Plant site/part mined	30.6 (yellow)

Mining continued on areas previously disturbed and has reached the setback limits this year on the east and south sides. Slope reconstruction will begin in 2021 once enough floor area is available to finish the toe of the slope.

10. No reclamation is required at this time.

18. The bond was evaluated in March 2017 and covers 40 acres of reclamation. The \$60,000.00 is adequate to cover the reclamation cost.