


Annual Report 2021

Ulrich-Rovedo Mine
DRMS Permit File M-2019-057
USFS 2810-021210-MPO-2019-003



Mining Area 1:

No Activity took place in Mining Area 1.

Mining Area 2:

New disturbance:

- Hole 8 (existing hole previously identified) - 100 sq/ft +/- Lat 39° 1.745'N, Long 105° 20.466'W
- Hole 24 (existing hole previously identified) - 100 sq/ft +/- Lat 39° 1.665'N, Long 105° 20.383'W

Reclamation Work:

- Hole 24 - 80% back filled.

Mining Area 3:

New Disturbance:

- Hole 20 (existing hole previously identified) - 100 sq/ft
- Hole 25 (Lat 39° 1.573'N Long 105° 20.629'W) - 100 sq/ft +/-

Reclamation work:

- Hole 21 - 50% back filled
- Hole 22 - 50% back filled

Noxious weed management was done in the way of 20 plants +/- of Common Mullein (*Verbascum Thapsus*) being pulled by hand or dug out with a shovel in mining area number 3 where indicated on the map.

Total New Disturbance - 300 sq/ ft +/- (or 0.01 acres)

Total reclamation - 200 sq/ft +/-

Noxious Weeds - 20 plants +/- pulled

Submitted by Jacob P Ulrich on 03/02/2022