

April 4, 2022

Geoff Niggeler Climax Molybdenum Company P.O. Box 68 Empire, CO 80438

Re: Climax Molybdenum Company; Henderson Mine; File No. M-1977-342; Technical Revision No. 35 (TR-35); Mill Water Treatment Plant Adequacy Review

Mr. Niggeler,

The Division of Reclamation, Mining and Safety (Division/DRMS) reviewed the contents of Technical Revision No. 35 (TR-35) - Mill Water Treatment Plant received on March 25, 2022 and submits the following comments.

 In Section 2.1 - Plant Location and Site Layout, the Operator states the detailed arrangement drawing and section for the interior of the WTP are provided as drawings...and 530-DD10-PLN-401. The Division did not receive drawing 530-DD10-PLN-401 with the technical revision submittal. The Division believes the Operator was referring to drawing 530-DD30-PLN-401, which was included in the submittal. Please provide the referenced drawing or revise the technical revision accordingly.

Please be advised the technical revision for the Henderson Mine may be deemed inadequate, and the revision may be denied on April 24, 2022, unless the above mentioned adequacy review items are addressed to the satisfaction of the Division.

If you have any questions, please contact me at peter.hays@state.co.us or (303) 866-3567 Ext. 8124.

Sincerely,

Peter S. Hays Environmental Protection Specialist

Ec: Jared Ebert; DRMS

