


PERMIT INFORMATION

Permit Number: C-1992-081 Mine Name: Hayden Gulch Loadout Operator: Hayden Gulch Terminal, LLC Operator Address: Ms Miranda Kawcak P.O. Box 670 Hayden, CO 81639	County: Routt Operation Type: Loadout Permit Status: Active Ownership: Private Operator Representative Present: Miranda Kawcak
Operator Representative Signature: (Field Issuance Only) 	

INSPECTION INFORMATION

Inspection Start Date: May 4, 2022 Inspection Start Time: 10:00 Inspection End Date: May 4, 2022 Inspection End Time: 11:00	Inspection Type: Coal Partial Inspection Inspection Reason: Normal I&E Program Weather: Clear	
Joint Inspection Agency: None	Joint Inspection Contacts: 	
Post Inspection Agency: None	Post Inspection Contacts: 	
Inspector(s): Tabetha Lynch	Inspector's Signature: 	Signature Date: 5/5/2022

Inspection Topic Summary

NOTE: Y=Inspected N=Not Inspected R=Comments Noted V=Violation Issued NA=Not Applicable

Y - Air Resource Protection
N - Availability of Records
N - Backfill & Grading
NA - Excess Spoil and Dev. Waste
NA - Explosives
N - Fish & Wildlife
Y - Hydrologic Balance
R - Gen. Compliance With Mine Plan
N - Other
NA - Processing Waste

Y - Roads
Y - Reclamation Success
N - Revegetation
NA - Subsidence
NA - Slides and Other Damage
NA - Support Facilities On-site
R - Signs and Markers
N - Support Facilities Not On-site
N - Special Categories Of Mining
Y - Topsoil

COMMENTS

This was a partial inspection of the Hayden Gulch Loadout; DRMS Permit No. C-1992-081, operated by Hayden Gulch Terminal, LLC. This inspection was conducted by Tabetha Lynch with the Colorado Division of Reclamation, Mining, and Safety (Division). No activity was occurring on site at the time of inspection.

Permit Revision No. 2 (PR-2) and Bond Release No.2 (SL-2) have been approved and issued by the Division. PR-2 modified the approved reclamation plan and post-mining land use for the major portion of the Hayden Gulch Loadout, consistent with the transfer of former rail spur areas to the Town of Hayden (Hayden) for recreational use. The former rail spur area has been converted to a recreational trail for the use of residents and visitors to Hayden under a locally managed "Tracks-to-Trails" program. The Division issued PR-2 on 12/27/21. The Division issued SL-2 on 2/17/2022.

GENERAL MINE PLAN COMPLIANCE:

Please mitigate weeds. White top, knapweed, and thistles were present during the inspection (photo below) primarily between Hwy 40 and hayfield.





Irrigation ditch in permit area north of Hwy 40

SIGNS AND MARKERS – Rule 4.02:

Signs were present as required. Below is the sign north of Hwy 40.



DOCUMENTS RECEIVED

OTHER (SPECIFY)

ENFORCEMENT ACTIONS/COMPLIANCE

No enforcement actions were initiated as a result of this inspection, nor are any pending.