

August 18, 2022

Robert M. Burger, P.G. Sierta Redcone, LLC 1885 Redcoach Road Allison Park, PA 15101 412-818-5659 r.burger@verizon.net

Elliott Russell Colorado Division of Reclamation, Mining and Safety 1313 Sherman Street, Room 215 Denver, CO 80203

Re: Revision of drill plan for MD-02, P-2014-003

Dear Mr. Russell,

Sierta is eliminating construction of Pads 7 and 8 and all proposed drilling at those pads as indicated in its Sierta, LLC Notice of Intent to Conduct Prospecting Operations Modification MD-02, P-2014-003. In addition, Sierta plans to drill two additional boreholes on Pad 6; one to a nominal depth of 1,200 feet and the other to a nominal depth of 600 feet. The locations and trajectories of the revised drilling plan are shown on the attached maps.

Thank you and all the best,


Sincerely,

cc: Dana Caccamise

Douglas Pride




Pad location for proposed drilling, Redcone Prospect



Source: USFS Montezuma quadrangle, 2014



Drill pad location with proposed boring trajectories





Footprint of drill pad 6





Revised drilling plan MD02 P2014-003

Robert Burger <r.burger@verizon.net>

Thu, Aug 18, 2022 at 9:16 AM

Reply-To: Robert Burger <r.burger@verizon.net>

To: "elliott.russell@state.co.us" <elliott.russell@state.co.us>

Cc: "amy.j.titterington@usda.gov" <amy.j.titterington@usda.gov>, "dana@caccamise.com" <dana@caccamise.com>, "pride.1@osu.edu" <pride.1@osu.edu>

Elliott,

Please see attached letter and maps of our revised plans for drilling at the Redcone Prospect.

Thanks and all the best, Robert

Robert M. Burger, P.G. 412-818-5659 r.burger@verizon.net

2 attachments

Revised drilling plan 2 MD-02 P2014-003.pdf 538K

2022-08-18 slides for NOI.pdf 1163K



Revised drilling plan MD02 P2014-003

Russell - DNR, Elliott <elliott.russell@state.co.us>

Fri, Aug 19, 2022 at 8:00 AM

To: Robert Burger <r.burger@verizon.net>

Cc: "amy.j.titterington@usda.gov" <amy.j.titterington@usda.gov>, "dana@caccamise.com" <dana@caccamise.com>, "pride.1@osu.edu" <pride.1@osu.edu>, Jason Musick - DNR <jason.musick@state.co.us>

Robert,

Thank you for the revised project update. It looks like you are requesting that one of the additional two boreholes, as discussed and approved in the July 31st Project Update, increase from a nominal depth of 600 feet to 1,200 feet. The Division sees no issue with this request as it still falls within the scope and bonding of MD2. No further permitting is required for this change at this time.

As a reminder, please provide the Division with Drill Hole Abandonment Reports (https://drive.google.com/file/d/14f___ RjXiPlumLHecNOyj5vTgmskO7evi/view) no later than 60 days after abandonment for drill holes that has artesian flow at the surface or no later than 12 months after abandonment of any other drill holes.

Please let me know if you have any questions.

Elliott Russell Environmental Protection Specialist Minerals Regulatory Program



I am working remotely and can be reached at 303.903.4456

Please note the Division's mailing address has changed

P 303.866.3567 x8132 | F 303.832.8106 | C 303.903.4456 Physical: 1313 Sherman Street, Room 215, Denver, CO 80203 Mailing: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216 Elliott.Russell@state.co.us | https://drms.colorado.gov

On Thu, Aug 18, 2022 at 9:17 AM Robert Burger <r.burger@verizon.net> wrote:

Elliott,

Please see attached letter and maps of our revised plans for drilling at the Redcone Prospect.

Thanks and all the best, Robert

Robert M. Burger, P.G. 412-818-5659 r.burger@verizon.net