

October 27, 2021

Colorado Department of Natural Resources Division of Reclamation, Mining, and Safety Attention: Minerals Program 1313 Sherman Street, Suite 215 Denver, Colorado 80203-2273

RE: Bulldog Mine Operation, Permit No. M-1977-215, Revision No. AM-02 Water Quality Monitoring Plan; surface water quality data

Minerals Program,

No surface water samples were taken in Windy Gulch in 2022 because there was no flow due to a lower than normal snowpack. Please include that no surface water samples were taken in 2022, in accordance with the Bulldog Mine Operation Environmental Protection Plan (EPP), Exhibit U.

Included are:

- 1) Figure 5 of Appendix 1
- 2) Sample location Map G-3
- 3) No Windy Gulch surface analytical results in 2022

Please call me at 208-209-1273 if you have questions.

Best Regards,

Randy McClure

Randy McClure Consultant Rio Grande Silver, Inc. 625 USFS Road 504.1A Creede, CO 81130 208-209-1273 rmcclure@hecla-mining.com