



October 31, 2022

Julie Mikulas, Regional Land Manager
Martin Marietta, Rocky Mountain Division
1800 North Taft Hill Road
Fort Collins, CO 80534

Re: S&H Mine, Permit M-2000-158, Receipt of Corrective Action Documentation

Dear Ms. Mikulas:

The Division received your response to a Compliance Problem cited in the Division's report from the inspection that was conducted on September 1, 2022. The status of the corrective action in regard to the cited problem is as follows:

Compliance Problem, Signs & Markers:

A sufficient mine identification sign was not posted at the entrance of the mine site.

This problem is considered to be resolved as a result of a photograph and letter from you, sent via email on October 28, 2022. The photograph shows the sign stating that a permit with the Division has been obtained and includes the permit number.

If you have any questions, please contact me at Rob.Zuber@state.co.us or by calling (720) 601-2276.

Thank you,

Robert D. Zuber, P.E.
Environmental Protection Specialist

Cc: Jason VonLembke, Scout Investments
Michael Cunningham, DRMS

