



November 4, 2022

Jared Ebert  
Division of Reclamation, Mining and Safety  
1313 Sherman St., Rm. 215  
Denver, Colorado 80203

Re: New Elk Mine  
Permit C-1981-012  
MR-132 Adequacy Review #3 Response

Dear Mr. Ebert

Please find electronically MR 132 Adequacy Review #2 Response.

**Rule 2.03.4 – Identification of Interests**

- A. The table showing owners has been revised on pages 9 and 10 to reflect the Jansen Loadout and Golden Eagle Fan Site.

**Rule 2.03.5- Compliance Information**

- B. The violation for Black Warrior Minerals, Inc. has been added to section 2.03.5.

**Rule 2.03.6 – Right of Entry Information**

- C. Page 11 has been revised to remove PR-5 from the text.
- 7. Page 12/13 has been revised to reflect the language approved with TR 76.

**Rule 2.03.10 – Identification of other Licenses and Permits**

- D. The footer on page 16 has been revised.

Please call or email if there are any questions or concerns.

Sincerely,

Nick Mason  
Engineering Technician