

January 12, 2023

Mr. Scott Harcus CEMEX, Inc. P.O. Box 529 Lyons, CO 80540

RE: Notice of Citizen Complaint, CT-5, Lyons Quarry; Permit File No. M-1977-208;

Dear Mr. Harcus,

The Division of Reclamation, Mining and Safety (Division/DRMS) received a complaint against the above referenced operation on January 11, 2023. A copy of the complaint letter and associated documentation has been enclosed for your records. Please provide the Division a Reclamation Cost Estimate pursuant to Rule 6.4.12 with sufficient detail for the Division to calculate the cost of reclamation of the site that would be incurred by the state. **The decision date for your response is set for March 13, 2023.** The Division is currently reviewing other aspects of the complaint along with a review of the permit and will contact you if it is determined that an inspection is warranted.

If you need additional information or have any questions, please contact me by telephone at **303-866-3567 x8114**, or by email at <a href="mailto:patrick.lennberg@state.co.us">patrick.lennberg@state.co.us</a>.

Sincerely,

Patrick Lennberg

**Environmental Protection Specialist** 

Enclosure: Complaint CT-5

cc: Jared Ebert, Division

ec: Scott Harcus, CEMEX, Inc., <a href="mailto:scotta.harcus@cemex.com">scotta.harcus@cemex.com</a>





## **DRMS Complaint Intake Tool**



By Submitting this form you are requesting an investigation of compliance with DRMS rules.

DRMS Internal Information		
Select Permit Type * Minerals		
Permit No List * M1977208		
Date of Complaint 01/11/2023		
COMPLAINANT INFORMATION	<u>^</u>	
*Indicates a Required Field		
Do you wish to remain anonymous? *		
○ Yes ● No		
Connection to Incident * Select all that apply		
Land Owner	☐ Mineral Owner	
✓ Nearby Resident  ☐ Other	Observed Incident	
DESCRIPTION OF COMPLAINT (Please be as specific as possible)	<u> </u>	
Note: Please provide as much detail related to location and issue as possible. Without enough detail, DRMS will not be able to process or investigate the complaint and, therefore, DRMS will have no choice but to discard the complaint.		
Location of Concern *		
Please provide as much detail as possible. It is important to and Section, physical address, or GPS location. You may als CEMEX Lyons 5134 Ute Hwy, Longmont, CO 80503 Lyons Quarry Permit M1977208	narrow down the location. If available, please include Township, Range o upload a pdf map below.	
Incident County *		
Boulder County		
Is this an ongoing issue(s)?		
● Yes ○ No		

Nature of Complaint *			
Select all that apply			
☐ Illegal Mining	□ Dust		
☐ Ground Water / Water Well Impact	☐ Acid or Toxic Materials/Spills		
☐ Surface Water Impact / Stormwater Management	☐ Property Damage		
☐ Mine Plan Compliance	☐ Waste Management / Dumping		
☐ Signs and Markers	Overburden / Development Waste		
☐ Financial Warranty	☐ Backfilling and Grading		
☐ Processing Waste / Tailings	<ul> <li>Processing Facilities</li> </ul>		
☐ Fish / Wildlife	☐ Erosion / Sedimentation		
☐ Off-Site Damage	Roads		
☐ Explosives / Blasting	Topsoi	I	
Revegetation	Weeds	5	
Reclamation Plan Compliance	Other	Inadequate Surety Bond; Process for Change to Reclamation Plan Not Followed	
Detailed description of the issue(s) * (?)			
Please provide as much detail as possible. It is important to narrow down the issue(s).  I am writing regarding the Lyons Quarry Permit M1977208.			
The current Reclamation Plan for Cemex Lyons includes a surety bond of approximately \$8.9MM, which is based on estimates from nearly 20 years ago. DRMS has previously indicated that this bond amount is likely inadequate in present day dollars and needs to be reassessed. Semi-related, the Reclamation Plan also now calls for the burial of concrete rubble and the onsite disposal of various materials, which is a significant modification to the Reclamation Plan and was approved via a Technical Revision in the 2001/2002 timeframe without an Amendment and the corresponding public notice process.			
In light of the above, specifically the modification to the Reclamation Plan without public comment and notice and the inadequacy of the surety bond, I believe that an Amendment process for the Lyons Quarry Permit M1977208 that includes a public notice process is warranted. The surety bond amount must also be increased to cover the current cost of reclamation as a figure not updated over the past 20 years, is surely inadequate. Given Cemex's poor performance in the stock market, and a current liquidity ratio of only 0.87 based on the three months ending September 30, 2022, I have serious concerns about their ability to pay for proper reclamation of their Lyons property, as a ratio of less than 1 typically means that a company is facing negative working capital, and may be experiencing a liquidity crisis.			
I am requesting an investigation and follow up from DRMS. Thank you for your time and attention. I look forward to hearing from you soon.			
Sincerely, Sarah Lorang			
Have you contacted the operator or party conducting the operation? If yes, please provide details. ★ ○ Yes  ○ No			
If known, please provide the name of the operato	r or party	conducting the operation.	
If known, please provide the Permit or NOI Number (ie M-1970-111 or P-1970-111).			
Must be entered in the following format: M1970111 or P1970111 (No dashes allowed) M1977208			
Have you contacted any other agencies or local governments related to this issue or issues? If so, please provide details. *  Yes No			

Are there supporting photos, maps, or documents you wish to upload?  ${\color{red}^*}$ 

O Yes 

No

What is your preferred method for DRMS to communicate with you throughout the investigation? \*

Select all that apply

☑ Phone ☑ E-mail ☑ US Mail