



Julie Mikulas  
Regional Land Manager

January 11, 2023

Mr. Peter Hays  
Division of Reclamation, Mining and Safety  
1313 Sherman Street, Room 215  
Denver, CO 80203

RE: Greeley 35<sup>th</sup> Ave, M-1977-036, Follow-up to Groundwater Monitoring Data Corrective Action

Dear Mr. Hays:

As a follow-up to your letter dated October 14, 2022:

CORRECTIVE ACTIONS: MW-1 and MW-2 have been damaged and monitoring well data has not been received. The Division will require the Operator to re-install the damaged monitoring wells and reinstitute monthly groundwater monitoring by January 13, 2023.

RESPONSE: I believe you are referring to Column 1 and Column 2 on our annual data submittal. These are MW-35TH AVE 7 and MW-35TH AVE 8.

MW-35TH AVE 7 is actually outside of our permit boundary in the rail line track right of way. As we discussed, we are evaluating where inside our permit we can place it with gas and powerline easement or possibly using an existing production well for the employee building.

MW-35<sup>TH</sup> AVE 8 is right in the path of our asphalt trucks and we are evaluating a better place to put it or using the existing production well for the office.

Please accept this letter as our request for an extension until 2/13/2023.

Please let me know if anything additional is needed.

Sincerely,

A handwritten signature in blue ink that reads "Julie Mikulas".

Julie Mikulas  
Regional Land Manager