

February 6, 2023

Division of Reclamation, Mining, and Safety
Department of Natural Resources
1313 Sherman St., Room 215
Denver, CO 80230

RE: Annual Report


Greetings,

There has been no new mining activity. Stockpiles are slowly being depleted above the area to be mined. With the extreme drought and piping of irrigation water the ground water content above the shale strata has receded substantially. Heavy snows in January deposited 32 inches of snow. This is a welcome event as grass seed from the planted areas was abundant in the dryland areas.

Weeds were sprayed in June in the hayfield and SW of the irrigation pond noted on the map. It is apparent the source is attributed at the inlet of the irrigation system.

An updated map and narrative letter was included. Satellite imagery was not included as an updated imagery wasn't available from Google Earth.

Thank you,



Rick Noland
President
Noland, Inc.