## **Stock Pond Inspection Form**

Time: Name Curre	of Insp nt Pane	pector: N. 700/05 el and XC Being Mined: 553 s) Being Inspected:
Yes	No	
		Is the stock pond within twice the projected angle of draw of subsidence? If yes, which pond(s):
		Are there visible surface cracks in or near the stock pond? If yes, describe (location, width, length, etc.):
		Is there any evidence of potential subsidence induced water loss? If yes, describe:
		Is there water in the pond? If yes, describe:
		Is mitigation needed? If yes, list suggestions:
Notes		•
	C	no access winter
Signature of Inspector: MUCOLI Fou LOS		

\* If any potential subsidence induced features are observed that could cause harm to the pond, notify Jessica Wilczek immediately.