

**STATE OF
COLORADO**

Reilley - DNR, Robin <robin.reilley@state.co.us>

Inspection Report 2023 May

Reilley - DNR, Robin <robin.reilley@state.co.us>

Fri, Jun 2, 2023 at 3:11 PM

To: "Green, Brian" <BCGreen@auroragov.org>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good Afternoon Brian,

Please find DRMS's 18 May 2023 inspection report attached.

Since vegetation was late emerging due to our cool, rainy spring and the presence of a nesting eagle, a partial inspection was carried out. My recommendation as to the best way forward given statutory timelines is for you to withdraw the SL for the time being and resubmit in August or so when we can do a complete walk through of the permit area. This gives the vegetation the summer to show itself more fully.

A resubmission would comprise the same information as that submitted in April.

I'm available to answer any questions or concerns that come up.

Thank you

Robin Reilley, M.S. GISP
Environmental Protection Specialist II



COLORADO
Division of Reclamation,
Mining and Safety
Department of Natural Resources

P 303.866.3567 ext 8105 |

F 303.832.8106

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

robin.reilley@state.co.us | <http://mining.state.co.us>

**Inspection_Supperior_SG_2023_05May.pdf**

1847K