



June 5, 2023

Bernard Buster
ELB Stone, Inc.
2493 CR 37 E
Lyons, CO 80540

Re: Buster Quarries, Permit M-1981-107, Receipt of Corrective Action Documentation

Dear Mr. Buster:

The Division received your response to a Compliance Problem cited in the Division's report from the inspection that was conducted on February 15, 2022. The status of the corrective action in regard to the cited problem is as follows.

Compliance Problem, Reclamation Success: The current reclamation plan needs to be updated and clarified pursuant to C.R.S. 34-32.5-116 (1). ELB Stone must describe how it intends to reclaim the large area of waste rock south of the #10 Quarry.

This problem is considered to be resolved as a result of the technical revision (TR-01) submitted on June 2, 2023.

If you have any questions, please contact me at Rob.Zuber@state.co.us or by calling (720) 601-2276.

Thank you,

Robert D. Zuber, P.E.
Environmental Protection Specialist

Cc: Michael Cunningham, DRMS

