



STATE OF  
COLORADO

Reilley - DNR, Robin <robin.reilley@state.co.us>

---

## Re: Pioneer Farm Mine Plan

1 message

---

**Reilley - DNR, Robin** <robin.reilley@state.co.us>

Fri, Sep 29, 2023 at 4:49 PM

To: Kurt THURMANN <kurt.thurmann@holcim.com>, Robin Reilley - DNR <robin.reilley@state.co.us>

Good afternoon Kurt,

I completely understand. Your extension is granted as attached.

**Robin Reilley, M.S. GISP**  
Environmental Protection Specialist II



**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural Resources

P 303.866.3567 ext 8105 |

F 303.832.8106

Physical Address: 1313 Sherman Street St., Suite 215, Denver, CO 80203

Mailing Address: DRMS Room 215, 1001 E 62nd Ave, Denver, CO 80216

[robin.reilley@state.co.us](mailto:robin.reilley@state.co.us) | <http://mining.state.co.us>

On Fri, Sep 29, 2023 at 10:49 AM Kurt THURMANN <[kurt.thurmann@holcim.com](mailto:kurt.thurmann@holcim.com)> wrote:

Hi Robin,

Yes, working on this but will need more time. See attached.

Thank you,

**Kurt Thurmman** | Environmental and Land Manager  
Mountain Region | Holcim - WCR, Inc.  
Mobile: (720) 329-8851  
1687 Cole Blvd., Suite 300  
Golden, CO 80401



**HOLCIM**

BUILDING PROGRESS FOR  
PEOPLE AND THE PLANET.

On Mon, Sep 25, 2023 at 11:35 AM Reilley - DNR, Robin <[robin.reilley@state.co.us](mailto:robin.reilley@state.co.us)> wrote:

Kurt,

As the corrective action is due by 30 September you may need more time. If you like, you could send me an extension of the date for the update of the mine plan.

Thank you  
Robin



**COLORADO**  
Division of Reclamation,  
Mining and Safety  
Department of Natural Resources

Mr. Kurt Thurman  
Environmental and Land Manager  
Holcim – WCR, INC.  
1687 Cole Blvd. Suite 300  
Golden, Co 80401

29 September 2023

**Re: Quincy/ Pioneer Farm; Permit M2000080  
DRMS Corrective Action, Update to Mine Plan**

Dear Mr. Thurman:

DRMS has extended the due date for the updated mine plan as requested. The new decision date will be 27 October 2023. Thank you for your attention to this permitting action.

Sincerely

Robin Reilley, M.S. GISP  
Environmental Protection Specialist II  
[Robin.reilley@state.co.us](mailto:Robin.reilley@state.co.us)





September 29, 2023

Robin Reilley  
Environmental Protection Specialist II  
Division of Reclamation, Mining & Safety  
1313 Sherman St., Room 215  
Denver, CO 80203

RE: Extension Request for Corrective Action Due Date, Pioneer Farm (Quincy) Permit No. M-2000-080

Ms. Reilley,

Holcim-WCR, Inc. ("Holcim") is requesting an extension to the Corrective Action due date stemming from the Succession of Operators inspection at the Pioneer Farm (M-2000-080) site. Holcim is requesting this extension to **October 27, 2023**. Holcim anticipates the affected area boundary markers to be replaced in the correct locations the week of October 2<sup>nd</sup>. Holcim will update the division once these are positioned. The Technical Revision ("TR") to the mine plan is in progress, however additional time is needed to prepare the TR. The Division has recently provided more clarification as to what the TR shall include.

If you have any questions, please feel free to contact me at [kurt.thurmann@holcim.com](mailto:kurt.thurmann@holcim.com).

Sincerely,

A handwritten signature in blue ink, appearing to read 'KURT', with a long horizontal line extending to the right.

Kurt Thurmann  
Environmental & Land Manager  
Holcim – WCR, Inc.



**Holcim\_Extension\_2023.pdf**

209K