

LEGEND

- Permit Boundary Terrace Ditch Postmining Contour Disturbance Boundary Cross Section Lines (See Map 20 and 20A) E E ST-A ST-A' Cross Section Lines (See Map 20B)
 - Post Mine Channel
 - Temporary Ditch

Note: Potentially affected areas are highwall mined areas under native lands based on a zero subsidence plan. Areas within the Disturbance Boundary may not be disturbed but are permitted for disturbance in the future. Please see Maps 19A for Gossard Loadout.



Affected Areas

Phase I Released Areas

Sediment Pond or Stock Pond (Constructed)

Stock Pond Location Not Constructed

W - ← -E 500





ENGINEERS CERTIFICATION I, LEE E. SAMPSON, hereby certify that this map has been reviewed by me and is true and correct to the best of my knowledge and information, relying on information supplied by experts employed by Colowyo Coal Company or qualified consultants working for Colowyo Coal Company, and that I am a Professional Engineer licensed in Colorado as required by the provisions of C.R.S. 12-25-101 through C.R.S. 12-25-119. IN WITNESS WHEREOF, I have hereunder set my hand and affixed my seal.



POSTMINING TOPOGRAPHY

COAL COMPANY SAFETY. PEOPLE - PRODUCTION - ENERGY COLORYO COAL COMPANY 5731 State Highway 13 Meeker, Colorado 81641		SCALE: <u>1" = 600'</u> DATE: <u>2/1/06</u> DRWG. BY: <u>TCP/ESI</u> APPROVED BY: DRWG NO. MAP 19			
No.	REVISION		DATE	BY	снк
TR-147	Revised Affected Area		4/26/21	Tony	AA
TR-147	Revised Affected Area East & West Pits		5/18/21	Tony	AA
TR-147	Revised Affected Area East & West Pits		5/24/21	Tony	AA
TR-155	Updated Permit & Disturbance Boundaries		8/15/22	Tony	Tony
TR-161	Updated PMT& Post Mine Drainages in South Taylor		10/23/23	Tony	LES