

November 20, 2023

Frank Leone Jr. 2400 E Main St Trinidad, CO 81082

Re: Inspection Problem Abatement Adequacy Review, Missing Affected Land Boundaries, Leone Gravel Pit #2, M-2006-085

On November 20, 2023, the Division of Reclamation, Mining and Safety (Division) received the enclosed responses to the following inspection problems cited in the Division's inspection report for the September 6, 2023 inspection of the Leone Gravel Pit #2:

- 1. **PROBLEM:** The current mine plan needs to be updated and clarified pursuant to C.R.S. 34-32.5-112 (1)(c)(VI). The Operator must provide sufficient information to describe or identify how the Operator intends to conduct the operation.
- 2. **PROBLEM:** The affected area boundary markers are missing. This is a problem for failure to maintain boundary markers around the affected area as required by Section 3.1.12(2) of the Rule.

Via email, the application page for a Technical Revision was received as a response to Problem #1. However, a Technical Revision is not considered submitted until the application page and fee are received by the Division. Per our phone conversation following your email, the fastest way to submit this is through e-permitting. Until the Technical Revision is submitted, this inspection problem is still considered **outstanding**, and is due on November 26, 2023.

Also via email, the Division received a map of the permit boundary with corners marked for the Biber Parcel Area. However, following the approval of the Acreage Reduction 1 (AR1) the 14.65 acre "Topsoil Area" and 31.14 acre "Unmined Area" in the Howell Parcel still remain within the permit as well. <u>To abate this issue, please verify in writing, via email, to the Division that affected land boundary markers have also been placed around these areas in addition to those in the Biber Parcel by the November 26, 2023 due date. If markers are not in place in the remaining Howell Parcel areas, and additional time is required to place these boundary markers, please submit an extension request to the Division via email.</u>

If you have any questions, please send me an email at <u>amber.gibson@state.co.us</u>, or call me at 720-836-0967.

Sincerely,



2010

Amber M. Gibson Environmental Protection Specialist I

Enclosure: Inspection Problem Responses from Operator

Cc: Jared Ebert, DRMS



Gibson - DNR, Amber <amber.gibson@state.co.us>

REVISION

1 message

LEONE SAND AND GRAVEL LLC <leonesrg@live.com> To: "Gibson - DNR, Amber" <amber.gibson@state.co.us> Mon, Nov 20, 2023 at 2:16 PM

Good afternoon Amber,

Here is the revision and photos. Please let me know if this will suffice or if we need to send anything else. Please let me know as soon as possible. If there is anything else we need, would you please call Frank as the deadline is Wednesday for us.

Thank you,

Chrissy Whalen Office Manager



Leone Sand & Gravel LLC Leone Ready Mix LLC 2400 E Main St Trinidad, CO 81082 719-846-4170 Office 719-845-0605 Fax

12 attachments



IMG_1526.jpg 137K



IMG_1531.jpg 144K



IMG_1532.jpg 174K



IMG_1536.jpg 189K



IMG_1537.jpg 185K



IMG_1539.jpg 159K



IMG_1540.jpg 196K



IMG_1541.jpg 184K



IMG_1542.jpg 182K



IMG_1543.PNG 945K



PIT PHOTOS.jpg 124K

₩ SKM_C3350i23112021360.pdf 186K



COLORADO DIVISION OF RECLAMATION, MINING AND SAFETY

1313 Sherman Street, Room 215, Denver, Colorado 80203 ph(303) 866-3567

REQUEST FOR TECHNICAL REVISION (TR) COVER SHEET

File No.: M- 2006 -085 Site Name: Leone Pit #2
County DAS Animas TR# (DRMS Use only)
Permittee: Leone Sand & Gravel LLC
Operator (If Other than Permittee):
Permittee Representative: Frank & Wayne Leone
Please provide a brief description of the proposed revision: I would like to increase
the maximum disturbed area from the current 60 acres to the 87
acres and bond the 87 acres (MAPS corners enclosed.)

As defined by the Minerals Rules, a Technical Revision (TR) is: "a change in the permit or application which does not have more than a minor effect upon the approved or proposed Reclamation or Environmental Protection Plan." The Division is charged with determining if the revision as submitted meets this definition. If the Division determines that the proposed revision is beyond the scope of a TR, the Division may require the submittal of a permit amendment to make the required or desired changes to the permit.

The request for a TR is not considered "filed for review" until the appropriate fee is received by the Division (as listed below by permit type). Please submit the appropriate fee with your request to expedite the review process. After the TR is submitted with the appropriate fee, the Division will determine if it is approvable within 30 days. If the Division requires additional information to approve a TR, you will be notified of specific deficiencies that will need to be addressed. If at the end of the 30 day review period there are still outstanding deficiencies, the Division must deny the TR unless the permittee requests additional time, in writing, to provide the required information.

There is no pre-defined format for the submittal of a TR; however, it is up to the permittee to provide sufficient information to the Division to approve the TR request, including updated mining and reclamation plan maps that accurately depict the changes proposed in the requested TR.

Required Fees for Technical Revision by Permit Type - Please mark the correct fee and submit it with your request for a Technical Revision.

Permit Type 110c, 111, 112 construction	<u>Required TR Fee</u>	Submitted (mark only one)
materials, and 112 quarries	\$216	X
112 hard rock (not DMO)	\$175	
110d, 112d(1, 2 or 3)	\$1006	

CORNER LOCATIONS

Amendment Mine area (Biber ownership)

Located in the SE $\frac{1}{2}$ SE $\frac{1}{2}$ of Section 31. The NW $\frac{1}{2}$ SW $\frac{1}{2}$, SE $\frac{1}{2}$ NW $\frac{1}{4}$ and SW $\frac{1}{2}$ NW $\frac{1}{4}$ and Parts of the SW $\frac{1}{2}$ NE $\frac{1}{4}$, NW $\frac{1}{2}$ SE $\frac{1}{2}$ SW $\frac{1}{4}$ and SW $\frac{1}{2}$ SW $\frac{1}{4}$, Section 32, Township 32 South, Range 62 West, and Parts of the NE $\frac{1}{4}$ NE $\frac{1}{4}$, NW $\frac{1}{4}$ NE $\frac{1}{4}$ and NE $\frac{1}{4}$ NW $\frac{1}{4}$, Section 6, Township 33 South, Range 62 West, 6th Prime Meridian, Las Animas County, Colorado.

The following description is based on bearings and distances found on the BLM Township plat for Township 32 South, Range 62 West, dated Dec., 1st, 1869 and Township 33 South Range 33 West, dated Dec., 1st, 1869 and is not a legal survey of the area.

Beginning at the Northwest corner of Section 32, T-32-5, R-62-W, 6th PM, marked with a 3/4" by 30" rebar with a $2\frac{1}{2}$ " cap marked IME, 2002, LS 18263; Thence south along the west line of Section 32, S00°07'22"E, 1510.64 feet to the true Point of Beginning (POB);

Thence S89°55'00"E, 3234.91 feet; Thence S09°29'38"E, 1543.26; Thence S59°25'26"W, 1781.64 feet; Thence S51°15'47"W, 2467.23 feet; to the southwest corner of said Section 32, also being the northeast corner of Section 6, T-33-S, R-62-W, 6TH P.M., marked with a 3/4" by 30" rebar with a $2\frac{1}{2}$ " cap marked, 2000, LS 12160.

Thence south, $504^{\circ}58'42''W$, 1170.99 feet; thence $589^{\circ}47'15''W$, 3303.44 feet; thence $N25^{\circ}34'42''E$, 1201.74 feet, to a point on the north line of said Section 6; thence east along said north line $N89^{\circ}13'26''E$, 1556.84 feet, thence $N00^{\circ}06'29''W$, 1388.30 feet; thence $N894^{\circ}7'00''E$, 1320.00 feet to a point on the west line of Section 32, T-32-S, R-62-W.

Thence north along said west line N00°27'00"W, 2647.69 feet to the True Point of Beginning. Said area containing 327.50 acres ±.

Total permit area 507.50 acres ±.

N89°13

58 84

twd.

303 44

37°12'16.9637"

104°23'05.8170"

37°12'06.3135"

104°23'12.9475"



phone: (719) 240-9424 | fax: (719) 583-0883





















